HAVPro

Human Vibration Meter



1060 Corporate Center Drive Oconomowoc, WI 53066 Tel: 800-245-0779 ● FAX:262-567-4047 http://www.quest-technologies.com

Copyright 2003

P/N 072-012 Rev. A

Table of Contents

Chapter 1	Introduction	1-1
	About This Manual	1-1
	Accessories	
	Selecting the Proper Transducer	
	·	
	Modes of Operation	
	Frequency Weighting Selection Band Limiting Filters	
Chapter 2	Getting Started	2-1
•	Menu Navigation	2-1
	Alpha Numeric Menu Function	
	Indexed Menu Function	
	Key Board Functions	
	Setup Key	
	Mode Selection	
	Averaging Time	
	Time History Settings	
	Store Time	
	Auto Store	2-7
	2nd History	2-8
	Vibration Mode Weighting	2-9
	Hand Arm Mode Weighting	
	Whole Body Weighting Mode	2-10
Chapter 3	Tools Menu	3-1
	Tools Key	3-1
	Accelerometer	3-1
	Display Units	3-2
	Integration	3-3
	Sum Factor X,Y, Z	3-4
	AC/DC Output	3-4
	AC/DC Output Settings	3-7
	Baud Rate	
	Handshaking	3-8

	Print History Selection	3-9
	Erase All Files	3-9
	Erase Setups	3-10
	Header 1,2,3	3-11
	Language	3-13
	Date and Time	3-13
Chapter 4	Range Menu	4-1
	Range Key	4-1
	Auto Range	4-1
	Gain X, Y, Z	
	Cal Level	
	Calibrate X, Y, Z	
	Sensitivity X, Y, Z	
	Reference Acceleration	4-5
Chapter 5	Printing	5-1
	Printer Cable	5-2
	Printing to a Windows Hyperterminal	5-2
Chapter 6	Storing and Recalling Data Files and S	Setups 6-1
	STORE Key	6-1
	Storing a Setup	
	Storing a File	
	Temporary Data Storage - File Register 00	6-5
	Data Storage - File Registers 01 thru 99	6-6
	Preserving the File Counter At Power-Off	6-6
	Recall Key	6-7
	Recalling a Setup	6-7
	Recalling Setup Register S0 at Power-On	
	Recalling a File	6-10
Chapter 7	Taking Measurements/ Viewing Data	on the
	HAVPro	7-1
	Run/Stop Key	7-1
	Overload Detection	
	Under-Range Indicator (?)	7-2

	Run-Interrupted Indicator (!)	7-3
	History Key	7-3
	Viewing Time History with 2nd History turned on	7-6
	Data Key	
Chapter 8	Powering the HAVPro	8-1
	Checking the Remaining Battery Voltage	8-1
	Installing New Batteries	
	Using External Power	
Chapter 9	Connections on the HAVPro	9-1
	Serial Interface Port	9-2
	Pinout	9-2
	Cables Used	9-3
	Transducer Connection	9-4
	Pinout	
	External Power Connection	
	Pinout	
	Quest Technologies Adapter	
	AC/DC Output Connector	
	Pinout	
Appendix A	Specifications	A-1
	General Characteristics	A-1
	Type Precision	A-1
	Effects of Temperature	A-2
	Effects of Humidity	A-2
	Limits of Temperature and Humidity	A-2
	Effects of Magnetic Fields	A-2
	Effects of Mechanical Vibrations	A-2
	Stabilization Time	A-2
	Data Storage	A-2
	Data Communications	
	Digital Display	
	Real-time Clock/Calendar	
	Run-time Clock	
	Power Supply	A-3

	Dimensions/Weight	A-3
	Declaration of Conformity	A-4
	Outputs	A-4
	Transducer Electrical Impedance	A-4
	Direct Input	A-5
	ICP® Input	A-5
	Charge Input	A-5
	Functions Measured	A-6
	Reference Acceleration	A-6
	Reference Calibration Frequency	A-6
	Reference Calibration Vibration	A-7
	Frequency Weighting Curves	A-7
	Fa (Flat 0.4 Hz to 100 Hz)	
	Fb (Flat 0.4 Hz to 1260 Hz) Frequency Weighting	
	Fc (Flat 6.3 Hz to 1260 Hz), Wh, and Ws Frequency Weighting.	
	Wb, Wc, and Wd Frequency Weightings	
	We,Wj, and Wk Frequency Weighting	
	Wg Frequency Weighting (Defined in BS6841:1987)	
	, , , , , , , , , , , , , , , , , , , ,	
	WB (Whole Body) Frequency Weighting	A-17
	Typical Measurements Ranges	
	Vibration - Fa	
	Vibration - Fb, Fc, Ws	A-20
	Hand Arm - Wh	
	Whole Body - WB	
	Whole Body - Wc	
	Whole Body - Wd, We	
	Whole Body - Wg	
	Whole Body - Wb, Wj, Wk	
	·	
Appendix B	Glossary	B-1
	Table of equations	B-1
	RMS Acceleration	B-1
	RMS Acceleration in Decibels	
	Allowed Exposure Time	B-2
	Energy Equivalent RMS Acceleration	
	Running RMS Acceleration LINEAR	
	Running RMS Acceleration EXPONENTIAL	
	~	

	Vibration Dose Value	B-3
	Maximum Transient Vibration Value	B-3
	Minimum Transient Vibration Value	B-3
	Long Term Maximum Peak	B-3
	Short Term Maximum Peak	B-4
	Long Term Crest Factor	B-4
	Short Term Crest Factor	B-4
	Summed Instantaneous Acceleration	B-4
Appendix	C Serial Interface Commands	C-1
	Setup and Query Commands	C-1
	Syntax for setup commands	
	Syntax for Query commands	C-2
	System Parameters (Q's and S's)	C-2
	Mode Specific Parameters	
	Read Data Commands	C-9
	Read Time History Commands	C-10
	Control Commands	
Appendix	D Frequency Response Curves	D-1
Appendix	E Miscellaneous Information	E-1
	DC Output Calibration	E-1
	AC/DC Outputs	
	DC Output	
	AC Output	
	Typical Measurement Ranges for Hand-Arm	
	Body Measurements	
	ICP Accelerometers	
	Typical Measurement Ranges for General Pu	
	Measurements	•
	ICP Accelerometers	
Appendix	F Service/Warranty Policy	F-1
		E 4
	Quest Service Policy	Г-Т

Introduction

Thank you for purchasing the Human Vibration Meter from Quest Technologies. The HAVPro is a powerful but small vibration measurement tool. This Handheld vibration analyzer will allow a variety of applications to be performed including; Whole Body Vibration analysis, Hand-Arm Vibration analysis, and general purpose vibration analysis.

This full featured vibration analyzer features 3 input channels, a sum channel, a variety of frequency weighting and band limiting settings, single and double integration, displayed data in a variety of units, and independent AC or DC outputs for all 3 channels simultaneously.

We invite you to read this manual to obtain the best results from your HAVPro.

About This Manual

This manual has 9 chapters and 5 appendices covering the following the topics:

Chapter 1 - Introduction

In this chapter we will discuss the functionality and capabilities of your HAVPro. We will also go into detail with regards to frequency weightings and screen and menu functionality.

Chapter 2 - Getting Started

This chapter will describe in detail the functionality and selections contained in the Setup menu.

Chapter 3 - The Tools Menu

This chapter will describe in detail the functionality and selections contained in the Tools menu.

Chapter 4 - The Range Menu

This chapter will describe in detail the functionality and selections contained in the Range menu. This includes calibration of the HAVPro.

Chapter 5 - Printing

This chapter will describe how to download data from the HAVPro.

Chapter 6 - Storing and Recalling Data Files and Setups

This chapter will describe in detail how to store data and setup information in the HAVPro's on-board memory.

Chapter 7 - Taking Measurements/Viewing Data on the HAVPro

This chapter will describe in detail how to use the Run/Stop key to take measurements, and how to view that data on the display of the HAVPro.

Chapter 8 - Powering the HAVPro

This chapter will describe the two ways in which to power the HAVPro.

Chapter 9 - Connections on the HAVPro

This chapter will describe all of the external connectors on the HAVPro.

Appendix A - Specifications

Appendix B - Glossary

Appendix C - I/O Commands

Appendix D - Frequency Response Curves

Appendix E - Miscellaneous Information

Accessories

Selection of the proper accessories for use with your HAVPro is one of the most important functions you can perform. The transducer is especially critical to obtaining good results.

The following accessories are available for your HAVPro:

- User Manual
- Batteries, 2 x AA, IEC Type LR6
- 072-005 Hand-Arm Block Mounting Adaptor
- 072-006 Computer Cable, HAVPro
- 072-007 Sensor Cable 1, for use with sensors 072-010/ 072-011
- 072-008 Carry Case, HAVPro
- 072-009 Power Supply: 90-264VAC to 12 VDC, 1.25 A
- 072-010 Triaxial Hand-Arm Accelerometer, PCB356A67
- 072-011 Triaxial Whole-Body Accelerometer, PCB356B40

Selecting the Proper Transducer

There are several important considerations when selecting a transducer to perform your measurements. The first decision that must be made is what type of transducer to use.

There are two general categories of accelerometers, ICP® and Charge.

- ICP® accelerometers are also called "Voltage Mode" or "Low impedance" and may be known by various other vendor trade names. ICP® is PCB's registered trademark which stands for "Integrated Circuit Piezoelectric" and identifies PCB sensors which incorporate built-in, signal conditioning electronics. The built-in electronics serve to convert the high impedance charge signal that is generated by the piezoelectric sensing element to a usable low impedance voltage signal which can be readily transmitted over ordinary 2 wire or coaxial cables to any voltage readout or recording device. The low impedance signal can be transmitted over long cable distances and used in dirty field or factory environments with little signal degradation.
- NOTE: The HAVPro has built-in ICP® power supplies and charge amplifiers. This will allow the HAVPro to interface directly with ICP® or charge transducers, and eliminates the need for external

signal conditioning.

Charge mode sensors output a high impedance, electrical charge signal that is generated by the piezoelectric sensing element. This signal is extremely sensitive to corruption from environmental influences. To conduct accurate measurements, it is necessary to condition this signal to a a low impedance voltage before it can be input to a readout or recording device. A charge amplifier or in-line charge converter is generally used for this purpose.

The final way to use the input of the HAVPro is through the direct input. This would require the use of some kind of external signal conditioning unit. An external source of ICP® power, or an external charge amplifier.

The next item to consider is the sensitivity of the transducer. The sensitivity of the accelerometer will depend on the application being performed. If the application is a high level application, a low sensitivity should be selected. For low level applications a high sensitivity accelerometer should be used.

NOTE: Transverse sensitivity is also something to be considered. Transverse sensitivity is defined as: The unwanted output signal of a motion sensor when subjected to motion perpendicular to the sensitive axis-usually expressed as a percent of the normal axis sensitivity. For example if you are using a tri-axial accelerometer and place an input signal on the Z axis, your X axis could also be reading a level even though there is really no x-axis signal present.

The resonant frequency of the transducer should also be considered. The resonant frequency is defined as the frequency at which the structure will readily vibrate. For accelerometers, there is one frequency where the accelerometer will vibrate much easier that at other frequencies. At this point, the reading will be very high, and could overload the input of the HAVPro. However, for most of the recommended accelerometers, the resonant frequency is well above the upper limit of the HAVPro, and will subsequently be masked out by the low pass filter on the HAVPro. If the resonant frequency becomes an issue, it is recommended that an external mechanical filter be used.

Frequency range is the next thing to take into consideration. Most recommended accelerometers will have a frequency range sufficient for use with the HAVPro. See the frequency response tables (appendix A) and graphs (appendix D) for more information on the HAVPro's frequency response.

The last thing to consider is temperature, humidity, and other physical agents, such as mounting surface, mass and environment. The mass of the accelerometer should ideally be no more that 1/50 of the mass of the object being measured. A ratio of as little as 1/10 is acceptable in extreme circumstances. The affect of these elements should always be considered when choosing a transducer. Please also be aware of the different methods of mounting an accelerometer and the affects of each of those methods on the measured data.

The following presents the specifications of the accelerometers provided with the HAVPro. Please contact Quest Technologies for information on other accelerometers.

Specification	Unit	072-010	072-011
Voltage Sensitivity	mV/g	10	100
Frequency Range (+/-5%)	Hz	0.5 to 3,000	0.5 to 1,000
Frequency Range (+/-10%)	Hz	0.3 to 5,000	
Mounted Resonant Frequency	kHz	≥25	≥27
Measurement Range	+/-g pk	500	10
Broadband Resolution (1 Hz to 10 kHz)	g rms	0.0005	0.0002
Shock Limit	+/-g pk	7,000	2,000
Operating Temperature Range	°F [°C]	-65 to +250 [-54 to +121]	+ 14 to 122 [-10 to 50]
Amplitude Linearity	%	≤ 1	≤ 1
Transverse Sensitivity	%	≤5	≤5
Strain Sensitivity	g/με	0.001	0.001
Excitation Voltage	VDC	20 to 30	6 to 30
Constant Current	mA	2 to 20	0.3 to 10
Output Impedance	ohms	<200	< 500
Output Bias	VDC	8 to 12	2 to 5
Discharge Time Constant	sec	1.0 to 2.0	1 to 3
Sensing Element	Type	Ceramic	Ceramic
Element Configuration	Structure	Shear	Shear
Electrical Connector	type/location	4-Pin/side	4-Pin/side
Housing	material/sealing	Titanium/Hermetic	Titanium/Welded
Mounting Thread	size	10-32 Female	10-32 Male

About the HAVPro

HAVPro is a powerful, all digital, Hand-Arm vibration analyzer. It features simultaneous 3 channel measurements, small lightweight design, easy to read display, portability utilizing 2 AA batteries, 115.2 kbps RS-232 interface, and

the capability to display and print text in a variety of languages.

Modes of Operation

The HAVPro is divided into three modes of operation. Each of these modes feature different frequency weighting selections as outlined later in this chapter.

Frequency Weighting Selection

To accommodate the multiple operating modes of the HAVPro, 13 different frequency weighting filters are available. The following table describes the frequency weighting options available in each of the operating modes. To select the frequency weighting for a particular mode, see the section in this manual titled Setup Key.

Mode	Frequency Weighting
Vibration	Ws (Severity) Fa (0.4 Hz to 100 Hz) Fb (0.4 Hz to 1250 Hz) Fc (6.3 Hz to 1250 Hz)
Hand Arm	W_h
Whole Body	$\begin{array}{c} WB \\ W_b \\ W_c \\ W_d \\ W_e \\ W_g \\ W_j \\ W_k \end{array}$

The Hand-Arm mode and the Whole body mode frequency weighting curves are defined in ISO 8041. The $W_{\rm g}$ frequency weighting curve is defined in British Standard 6841:1987.

In addition to defining the frequency weightings for Hand-Arm and Whole Body, ISO 8041 also defines a band-limiting filter to be used with each of the frequency weightings. Each band-limiting filter is a combination of a high-pass and low-pass 2nd order Butterworth filter, 12 dB per octave attenuation, with - 3 dB corner frequencies at the frequencies listed in table 3 below. When a frequency weighting is selected in the HAVPro Hand-Arm mode, or Whole Body mode, the HAVPro automatically places both the weighting filter and the appropriate band-limiting filter in the signal path.

Weighting	Band-Limiting Filter
W _h	6.3 to 1250 Hz
$ W_{b,}W_{c,}W_{d,}W_{e,}W_{j,}W_{k} $	0.4 to 100 Hz
WB, Wg	0.8 to 100 Hz

2

Getting Started

This section will introduce you to the keypad and functionality of the HAVPro.

Menu Navigation

Navigating through the HAVPro menus is similar to navigating through other Quest Technologies instruments. The menus are arranged in lists. The appropriate menu key is used to enter the menu, and then the Lup and Down arrow keys are used to scroll through the menu. When you come to a setting you want to change, press the Enter key shown below.




Note: For the remainder of this manual, references to the Enter key refer to this key located in the center portion of the instrument keypad.

This will permit you to enter the modify section of the menu. You can now use the Right and Left arrow keys to scroll through the options for that item. After the appropriate selection is in the window, use the Enter key to select that setting. This will place you back into the main menu where once again the Lup and Down arrow keys can be used to navigate.

Alpha Numeric Menu Function

The Alpha numeric menu screens include the Header screens and the Calibrator sensitivity screen. These are settings that require the user to enter letters of the alphabet or numerals into the field. To change an alpha numeric menu setting,

Step 1 Go to the menu item you wish to change.




Step 2 Press the Enter key to place the HAVPro into the modify mode. The selection will begin to blink.



Step 3 Use the and arrow keys to select a position to modify.



Step 4 Use the ▲ and ▼ arrow keys to select the character you want in that position.



Step 5 Use the and arrow keys again to move to the next position. When you move to the next position, the HAVPro will start you from where you left off. (i.e. if you entered an 'F' in the first position, when you move to the next position, you will be starting from the 'F' on that position.

```
Header 1
Wil■
```

Step 6 Hit the Enter key or move to the next menu item to accept the change. Anytime you have made a change, the change will automatically be accepted even if you don't hit the Enter key. You can accept the change just by moving to another section of the HAVPro.

```
Header 1
Wilson Processin
```

The following is an example of how to make a change to an indexed menu item. (An item that has a specific list of choices.)

Step 1 Go to the setting you wish to change.

Operating Mode Vibration

Step 2 Press the Enter key to place the HAVPro in the modify mode. The selection will begin to blink.

Operating Mode Vibration

Step 3 Use the **④** and **▶** arrow keys to scroll through the selections in the menu.

Operating Mode Vibration

Operating Mode Hand Arm

Operating Mode whole Body

Step 4 When you come to the selection you desire, stop scrolling.

Operating Mode Whole Body

Step 5 To accept the change, either hit the Enter key or move to the next menu item or to another part of the HAVPro.

Operating Mode Whole Body

Key Board Functions

The keyboard on the front of the HAVPro is the main interface to the instrument. The keyboard consists of 11 dedicated function keys, 4 arrow keys and the Enter key shown below..





In the following section, we will describe the functionality and selections associated with each key.

Setup Key

The **SETUP** key places you into the Setup menu. This menu is used to set general system parameters such as operating mode and frequency weighting. The selections available in the Setup menu are described below. The Setup menu is a circular menu. You can scroll through and return to the top by continuously pressing the \bigcirc or \triangle arrow key.


Mode Selection

Hint: This setting is in the Setup menu. To access the Setup menu press the

SETUP key and then use the **△** and **▽** arrow keys to navigate

through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. This section is used to set the operating mode. The selections are Whole body, Hand Arm or Vibration.



Hint:

This setting is in the Setup menu. To access the Setup menu press the **SETUP** key and then use the $extbf{ iny and } extbf{ iny arrow keys to navigate}$ through the menu items.

NOTE: An exponential detector is defined as a detector that maintains a moving average of the signal. The only exponential detector in the HAVPro is the Slow detector. This detector will begin by taking a 1 second average. As time moves, the exponential detector will discard the first part of the average, as the next part is collected. A linear detector will take the signal and average over the averaging time, and then start over. All previously collected samples are disregarded in the new linear average.

The averaging time refers to the amount of time data is collected and averaged before a new average is started. The selections are Slow, 1 sec, 2 sec, 5 sec, 10 sec, 20 sec, 30 sec, and 60 sec. The Slow response is a 1 second exponential detector, while the others are linear repeat type averages. The averaging is the same for all Operating modes.

Time History Settings

NOTE: To view each selection, first press the Enterey, and then press the or arrow key to scroll through each selection. The Averaging time is also used to determine the rate of storage for the Time History. The Time History will store the Arms value along with the Peak value if the user desires, for the X, Y, Z, and Sum channels. The Time History buffer is limited to 240 samples, 120 samples if the Peak value is selected. To setup Time History Peak storage, see the 2nd History menu section below.

The following are the selections you would encounter when changing the Averaging Time:

Averaging	
Slow	
Averaging	
1 sec	
Averaging	
Averaging 2sec	

Averaging
10 sec

Averaging
20 sec

Averaging
30 sec

Averaging
60 sec

Store Time

Hint: This setting is in the Setup menu. To access the Setup menu press the **SETUP** key and then use the **△** and **▽** arrow keys to navigate through the menu items.

NOTE: To change the Store Time parameters, press the Enter key, use the and arrows to select the desired value, and then use the and arrows to move to the next position. Once all positions are set press the Enter key or move to any other part of the HAVPro to accept the entry.

The Store Time selection works in conjunction with the Auto Store setting. The Auto Store setting will allow you to automatically store measurement data at a rate indicated by the Store Time. The Store Time can be set from 1 minute to 99 hours.

Store Time hh:mm 00:00

Auto Store

Hint: This setting is in the Setup menu. To access the Setup menu press the SETUP key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

NOTE: The data memory in the HAVPro is a non-volatile EEPROM chip. Even if the batteries go dead for an extended period of time, the stored setups and data will be retained.

The Auto Store function in the HAVPro will allow you to store data over time. The Store Time is the rate at which the data will be stored. At the end of the store time the Auto Store function will store any history data that has been collected, as well as the overall data from all three channels and the sum channel. The data will be stored as a file in the memory. After the data is stored, the instrument is reset

automatically and a new set of data is collected. The limitation on the memory is 100 files. When the memory reaches the maximum number of files, it will stop storing data.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection.

There are three selections in the Auto Store menu:



The Auto Store is turned off with this setting.



The Auto Store feature will store each time the Store Time is reached. This will continue until all file registers are full.

The Auto Store-Autostop feature will allow you to take a fixed length measurement. The Autostop feature will stop the meter when the Store time is reached, just as if you had pressed the (A) key.

2nd History


Hint:

through the menu items.

This setting is in the Setup menu. To access the Setup menu press the **SETUP** *key and then use the* **(a)** *and* **(b)** *arrow keys to navigate*

> The 2nd History setting will allow you to store a Peak value along with the Arms value that is automatically stored in the Time History buffer. The Peak will be stored for all three channels and the Sum channel. Turning on the 2nd value will cut the number of sample storage space from 240 samples to 120 samples.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. In the 2nd history selection menu you have the choice of None or Peak.



Vibration Mode Weighting

Hint: This setting is in the Setup menu. To access the Setup menu press the SETUP key and then use the ♠ and ♥ arrow keys to navigate

through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. In the vibration mode you can select from the following weighting selections. Please see the appendix at the end of this manual for details on weighting curves. The weighting selection is independent for all channels. Here we only depict the X channel data, but the other channels screens would be the same:

Weighting X
Fa 0.4-100 Hz
Weighting X
Fb 0.4-1250 Hz
Weighting X
Weighting X Fc 6.3-1250 Hz
5 5

Hand Arm Mode Weighting

As required by ISO 8041 the Hand Arm mode has only one weighting selection. Please see the appendix at the end of this manual for details on this weighting curve. The

weighting curve is labeled as Wh. This weighting selection is for all channels and the sum channel. Because there is only one selection in the Hand Arm mode, the weighting selection is not present on the Setup menu.

Whole Body Weighting Mode

Hint: This setting is in the Setup menu. To access the Setup menu press the SETUP key and then use the ▲ and ▼ arrow keys to navigate

through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. In the Whole Body mode you can select from the following weighting selections as required by ISO8041. Please see the appendix at the end of this manual for details on the weighting curves. The weighting selection is independent for all channels. Here we only depict the X channel data, but the other channels screens would be the same:

Weighting WB	X
Weighting Wb	X
Weighting Wc	X
Weighting Wd	X
Weighting We	X
Weighting Wg	X
Weighting Wj	X

NOTE: The Wg frequency weighting curve is defined in BS 6841:1987.

Weighting X Wk

3

Tools Menu

The Tools menu has settings relating to the transducer and setup information relevant to the instrument. Selections include communications, printing, headers, etc.

Tools Key

The tools menu functions in exactly the same manner as the Setup menu and has the following selections:

Accelerometer

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the $extbf{ riangle}$ and $extbf{ riangle}$ arrow keys to navigate through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. This will allow you to select the type of transducer you wish to use. The selections are ICP®, Direct, and Charge. These refer to the type of accelerometer being used.

Accelerometer Direct

The Direct setting is used to input a direct signal from a transducer. No operational power is provided to the transducer.

Accelerometer ICP XDC=10.0V

The ICP® setting will provide a 28 Volt 2mA constant current to each of the three input channels, in order to power up to three accelerometers. This is used with ICP® type accelerometers. The voltage reported on this screen is a monitoring of the ICP® power being provided to the transducer. When the transducer is not connected, this voltage will read 25 to 26 volts. If you have a transducer connected and it is working properly, it should be reading between 2 and 12 volts depending upon the transducer.

If the reading is 0, then the ICP® power could be shorted to ground or have some other problem. Check all connections, cables, and connectors.

Accelerometer Charge

This setting would be used to amplify the signal from a charge type accelerometer.

Display Units

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the **and arrow** keys to navigate through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the
or
arrow key to scroll through each selection. The Display Units setting controls how data is displayed and printed by the HAVPro. The HAVPro can display data in six different formats. The selection of the display units will apply to all three channels and the sum channel. All channels will have the same units. The choices are: m/s^2 , cm/s^2 , ft/s^2 , in/s^2 , g, and dB.

NOTE: The HAVPro uses a reference acceleration of 10^6 m/s² (velocity reference = 10^9 m/s, displacement reference = 10^{12} m) or a reference of 10^5 m/s² (velocity reference = 10^{18} m/s, displacement reference = 10^{11} m) to display acceleration, velocity and displacement in dB units. Please see the section in the RANGE key for details on changing the reference acceleration.



Display Units
ft/s²

Display Units
in/s²

Display Units
g

Display Units
dB

Integration

Hint: This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

NOTE: Integration is a mathematical process of changing the displayed units from acceleration to velocity to displacement. Single integration changes the displayed parameter from acceleration to velocity by dividing the acceleration by: $2\pi f$ (i.e. ft/s^2 to ft/s). Double integration changes the parameter from acceleration to displacement by dividing the acceleration by: $4\pi^2 f^2$ (i.e. m/s^2 to meters).

Integration applies only to the Vibration mode. There is no integration available in the Hand Arm or Whole Body Modes. Integration is the process of converting the data from acceleration, which is the standard method of displaying the data, into velocity and displacement.

Integration
None
Integration
Single
Integration
Double


NOTE: To view each selection, first press the Enter key, and then press the \bigcirc or \bigcirc arrow key to scroll through each selection.

Single integration will express the units in velocity, and double integration will express the units in displacement.

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the $extbf{ iny}$ and $extbf{ iny}$ arrow keys to navigate through the menu items.

In the process of calculating the sum quantities (the data that appears under the Σ menu) the HAVPro multiplies the instantaneous acceleration for each channel by a scaler factor (sometimes called a k-factor). The HAVPro allows the user to select a different k factor for each channel. The default setting is 1.00; however; some applications may require different settings.



NOTE: To change the Sum Factor parameter, press the Enter key, use the and rows to select the desired value, and then use the and arrows to move to the next position. Once all positions are set press the Enter key or move to any other part of the HAVPro to accept the entry.

The applications that require the Sum Factor to be altered are specified in certain ISO standards. If you are not trying to measure according to any specific standard, the appropriate setting for this parameter is 1.00.

AC/DC Output


Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the **and arrow** keys to navigate through the menu items.


The AC/DC outputs on the HAVPro are independent and simultaneous for all three channels. First we will discuss the output in general, and then give the specific settings for the AC/DC outputs.

NOTE: To view each selection, first press the Enter key, and then press the \bigcirc or \bigcirc arrow key to scroll through each selection. AC output is useful for frequency analysis by an external analyzer or for recording in a tape recorder. The DC output is useful for a chart recorder, or to measure the voltage proportional to the RMS or peak value.

The DC output is updated according to the averaging time. If the averaging time is set to slow, the signal on the DC output pin for the selected channel will be updated once per second. If the averaging time is set to 60 seconds, the signal on the DC output pin for the selected channel will be updated once every 60 seconds.



The AC/DC output connector is a 5 pin switchcraft connector located on the bottom edge of the instrument. The pinout is as follows:



Pin#	Description
1	Ground
2	X - Axis AC/DC Output
3	Y - Axis AC/DC Output
4	No Connection
5	Z - Axis AC/DC Output

The signal that is output on each pin is selectable for each channel. The selections are the same for each channel. We will list the X channel selections, however the available selections will be the same for all operating modes as well.

The AC output will produce a signal from 0 - 0.5 Volt RMS.

The scale of the DC output is typically 5 mV/dB. The level Typically varies between 0 Vdc to ± 1.0 Vdc.

AC/DC Output Settings

The weighting filters work in con-junction with the handlimiting filters

junction with the bandlimiting filters. See page 1-7.	Setting	Description
AC/DC Output X AC: Weighted	AC: Weighted	This will weight the output pin for the selected channel according to the weighting selected for that channel. If Channel X has a weighting of Ws, then the output pin for Channel X will produce a Ws weighted AC signal.
AC/DC Output X AC: BandLimit	AC: Band- Limit	This will weight the output pin for the selected channel according to the Band Limiting filter, specified in chapter 1, for that channel. For example if Channel X has a weighting of Wh, then the output pin for Channel X will produce a band limited (6.3 to 1250 Hz) AC signal.
AC/DC Output X DC: rms	DC: rms	This signal will be a DC voltage with a level proportional to the RMS level displayed on the HAVPro.
AC/DC Output X DC: min	DC: min	This signal will be a DC voltage with a level proportional to the min level displayed on the HAVPro.
AC/DC Output X DC: max	DC: max	This signal will be a DC voltage with a level proportional to the max level displayed on the HAVPro.
AC/DC Output X DC: peak	DC: peak	This signal will be a DC voltage with a level proportional to the peak level displayed on the HAVPro.
AC/DC Output X DC: rms Σ	DC: rms Σ	This signal will be a DC voltage with a level proportional to the RMS sum level displayed on the HAVPro.
AC/DC Output X DC: min Σ	DC: min ∑	This signal will be a DC voltage with a level proportional to the min sum level displayed on the HAVPro.
AC/DC Output X DC: max Σ	DC: max ∑	This signal will be a DC voltage with a level proportional to the max sum level displayed on the HAVPro.
AC/DC Output X DC: peak Σ	DC: peak ∑	This signal will be a DC voltage with a level proportional to the peak sum level displayed on the HAVPro.

Only one selection can be made for each channel. Channels Y and Z will have the same selection of settings. The weighting selected can be independent for each channel.

Baud Rate

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the $extbf{ iny}$ and $extbf{ iny}$ arrow keys to navigate through the menu items.

The Baud rate selection will allow you to communicate with the PC or the serial printer. The choices are as follows:

Baud Rate
2400
Baud Rate
9600
Baud Rate
Baud Rate 38.4k

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. It is important that the setting on your computer or on the serial printer match the Baud Rate setting of the HAVPro.

Handshaking

The handshaking on the HAVPro is defaulted to hardware (DTR) handshaking.

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the **(A)** and **(T)** arrow keys to navigate through the menu items.

The print history selection will determine whether or not the HAVPro will send the History Buffer information when the **PRINT** key is pressed.

Print History Yes

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection. This selection will cause the HAVPro to send data contained in the History buffer to the printer.



With this selection, the HAVPro will only send the overall data from the 3 input channels and the sum channel.

Erase All Files

Hint:


This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the **(A)** and **(T)** arrow keys to navigate through the menu items.

This allows you to clear the measurement files from the memory of the HAVPro. The memory in the HAVPro is a non-volatile memory. If the batteries go dead, the measurement files will not be lost. The only way to clear out the file registers is to use the Erase All files menu.

This command will not clear the current measurement, or the current history buffer information. The ② Reset key is used for that purpose. This command will only clear the file registers. NOTE: To view each selection, first press the 0 key, and then press the b or d arrow key to scroll through each selection.

To clear all files:

- **Step 1** Go to the Erase All Files menu item.
- **Step 2** The following screen will appear. Press the Enter key. The 'No' will start to flash. Press the key to change the screen to 'Yes'.



Step 3 The following screen will now be showing and the 'Yes' will be flashing. Press the Enter key to erase the files.



Step 4 After pressing the Enter key, the screen will display the following message. After about 3 seconds the display will return to the Erase All Files screen.



All file registers have now been cleared.

Erase Setups

Hint: This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

The HAVPro has the ability to store 10 setups internally in the memory. This is accomplished, as explained later in the manual, by pressing the **STORE** key while in the setup menu. The Erase Setups command is used to clear all of the stored setups from the setup registers.

NOTE: To view each selection, first press the Enter key, and then press the
or
arrow key to scroll through each selection. To clear all setups:


- **Step 1** Go to the Erase Setups menu item.
- **Step 2** The following screen will appear. Press the Enter key. The 'No' will start to flash. Press the key to change the screen to 'Yes'.



Step 3 The following screen will now be showing and the 'Yes' will be flashing. Press the Enter key to erase the setups.



Step 4 After pressing the Enter key, the screen displays the following message. The display will return to the Erase Setups screen after about 3 to 10 seconds.



All Setups have now been cleared from the setup registers.

Header 1,2,3


Hint: This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

The HAVPro has 3 Heading information screens. This will allow you to enter descriptive information into the instrument, that will then be printed out with the reports. The


information can be up to 16 characters in length in each screen.

To enter information in the Header screens, follow these directions:

Step 1 Go to the Header that you wish to change.



Step 2 You will have either a blank screen, or a screen that has previously entered information.



Hint: You can use the reset key to erase all of the existing entries in an alphanumeric entry. Position the cursor on the Left most position you want erased. Press the ② key, and all positions to the right of the cursor, including the cursor position will be erased. If the cursor position is all the way to the left, the entire screen will be erased.

NOTE: The HAVPro will remember the previously selected character as you move positions. If you enter a 'K' in the 1st position, when you use the ① or ① arrow key to move the next position, you will begin from the 'K'.

NOTE: To change the Header, press the Enter key, use the ♠ and ♥ arrows to

select the desired value, and then use the **b** and **d** arrows to move to the next position. Once all positions are set press the Enter key or move to any other part

of the HAVPro to accept the entry.

- Step 3 Use the **④** and **▶** arrow keys to select the position you want to change, and use the **♠** and **▼** arrow keys to change the character in that position.
- **Step 4** When you have completed all the entries, press the Enter key to return to the Tools menu. You can now move onto the next header (Header 2) by pressing the ▼ arrow key.

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the $extbf{ iny}$ and $extbf{ iny}$ arrow keys to navigate through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the \bigcirc or \bigcirc arrow key to scroll through each selection.

The HAVPro can only store four different languages at one time. Contact Quest Technologies for information on available language packages. The HAVPro has the ability to display and print in several different languages. The choices are English, Spanish, Italian, French, German, Portuguese, Czechoslavakia, and Dutch. Below is an example of one of the language options:



Date and Time

Hint:

This setting is in the Tools menu. To access the Tools menu press the **TOOLS** key and then use the **(A)** and **(T)** arrow keys to navigate through the menu items.

NOTE: To change the Date and Time parameter, press the Enter key, use the and arrows to select the desired value, and then use the and arrows to move to the next position. Once all positions are set press the Enter key or move to any other part of the HAVPro to accept the entry.

The date and time functions can be set in this menu. To set the date and time, go to this menu item. Press the Enter key. You can now make changes just like the alphanumeric menu items in the Header screens. Once all changes have been made, press the Enter key again to confirm the changes.

Date 00:00 01 Jan 99



Range Menu

The **RANGE** key functions are concerned with the level of input signals coming into the HAVPro.

Range Key

In this menu, Gain is added, Calibration is performed, Auto-Ranging is enabled, and Accelerometer Sensitivity is entered.

Auto Range

Hint:

This setting is in the Range menu. To access the Range menu press the **RANGE** key and then use the \triangle and ∇ arrow keys to navigate through the menu items.

The Auto-Range function in the HAVPro is designed to work with a steady state signal. It is not meant for use while taking data. Before enabling this function, the transducer should be attached to the steady state vibration to be measured. Next, find the Auto-Range display, located in the Range menu. Press the Enter key to enable auto-ranging. The HAVPro will use its Auto-Range algorithm to adjust the gain for all three channels such that the steady state input signal can be properly measured by the HAVPro. (The gain is adjusted so that the signal falls within the top 20 dB of the HAVPro's analog to digital converter's range.)

The selections for the gain will be either 0, 20, 40, or 60 dB.

Once the gain selection is stable, press the Enter key to save the settings. The HAVPro must be stopped and reset before the Auto-Range function can be used.

Gain X, Y, Z

Hint:

This setting is in the Range menu. To access the Range menu press the RANGE key and then use the and rarrow keys to navigate through the menu items.

select one channel at a time, and manually assign a gain setting to that channel. The choices are 0, 20, 40, or 60 dB.

To set the Gain for the X channel, first press the **RANGE**

NOTE: To view each selection, first press the Enter key, and then press the \bigcirc or \bigcirc arrow key to scroll through each selection. To set the Gain for the X channel, first press the **RANGE** key to open the Range menu. Next press the \bigcirc arrow key once to view the Gain X parameter. Press the Enter key to enter the change mode, use the \bigcirc or \bigcirc arrow keys to select the desired value, and press the Enter key again to confirm the change. The Gain Y and Gain Z displays are located just below the Gain X display. (From the Gain X display press the \bigcirc arrow key once to view the Gain Y display. Press the \bigcirc arrow key again to view the Gain Z display.)

The Gain settings in the HAVPro will perform manually what the Auto-Range setting did automatically. You can

Gain X 40 dB **Hint:** This setting is in the Range menu. To access the Range menu press the **RANGE** key and then use the **△** and **▽** arrow keys to navigate through the menu items.

NOTE: Calibrators operate at a variety of frequencies. It is important that the frequency weighting selection does not affect the level of the calibration. In general it is recommended to calibrate in the Vibration mode, using the Fc frequency weighting. This will only apply a bandlimiting filter from 6.3 Hz to 1250 Hz. This should accommodate most vibration calibrators.

The Cal Level screen will allow you to enter the operating level of your calibrator. The frequency of the calibrator is also important, please see the adjacent note. To enter a value for your calibrator, go to the cal level screen, press the Enter key, use the and arrow keys to select the position and use the and arrow keys to change the characters. When the proper level is entered, press the Enter key to return to the Range menu. The level must always be entered in g's (rms).

Cal Level 1.000e+00 g rms

NOTE: To change the Cal Level parameter, press the Enter key, use the (a) and (b) arrows to select the desired value, and then use the (b) and (d) arrows to move to the next position. Once all positions are set press the Enter key or move to any other part of the HAVPro to accept the entry.

During calibration the gain of the HAVPro should also be set so that the level of the calibrator is within the HAVPro's measurement range. For example, when using a 1.0 g rms calibrator and an accelerometer with a sensitivity of approximately 100mV/g, the gain should be set to 20 dB. For a 10 mV/g accelerometer, the gain should be set to 40 dB. A gain of 60 dB is appropriate for a 1 mV/g accelerometer. See appendix A for a complete listing of the HAVPro's measurement range.

Calibrate X, Y, Z

Hint:

This setting is in the Range menu. To access the Range menu press the **RANGE** key and then use the \triangle and \bigcirc arrow keys to navigate through the menu items.

The calibrate screens are used to calibrate individual channels using a calibrator attached to the accelerometer. To calibrate the HAVPro with the accelerometer's published sensitivity, see the next section in this manual. To calibrate:

During stabilization (i.e. after the Enterkey has been pressed once), the calibration can be cancelled by pressing the on/off key.

Step 1 Enter the menu for the channel you wish to calibrate.

Step 2 Make sure the transducer for channel X is firmly attached to the calibrator.

Step 3 Start the calibrator.

Step 4 Press the Enter key on the HAVPro. The screen will start to flash values. When the level of your calibrator appears in the screen, and the reading is stable, press the Enter key again.

NOTE: After a given channel has been calibrated using the shaker type calibrator, the HAVPro calculates the sensitiveity of the attached accelerometer. To view the sensitivity please see the next section in this manual.

This will calibrate channel X of the HAVPro. Repeat the procedure for the channels Y and Z. The Calibrate Y and Calibrate Z displays are located just below the Calibrate X display. (From the Calibrate X display press the \odot arrow key once to get to the Calibrate Y display, and press the \odot arrow key again to get to the Calibrate Z display.)



NOTE: If the integration setting is set to single or double, the HAVPro will not calibrate using a calibrator. Specifically, the Cal Level, Calibrate X, Calibrate Y, Calibrate Z menu items will not be displayed.

Sensitivity X, Y, Z

Hint:

This setting is in the Range menu. To access the Range menu press the RANGE key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

Another method of calibrating the HAVPro is to use the published sensitivity of the accelerometer. This is accomplished through the Sensitivity menu item.

NOTE: To change the Sensitivity parameter, press the Enter key, use the (a) and (b) arrows to select the desired value, and then use the (b) and (d) arrows to move to the next position. Once all positions are set press the Enter key or move to any other part of the HAVPro to accept the entry.

To enter the sensitivity of the accelerometer, go to the menu item for the desired channel. Press the Enter key to enter the change menu, use the ▶ and ♠ arrow keys to select the position you wish to change, and the ♠ and ♥ arrow keys to change the characters. When the correct sensitivity has been entered, press the Enter key to confirm the change. The entry procedure is the same for all channels, and the screens will look the same. The units for ICP® and Direct are mV/g (rms), the units for charge accelerometers are pC/g (rms).

Reference Acceleration

Hint: This setting is in the Range menu. To access the Range menu press the **RANGE** key and then use the ♠ and ♥ arrow keys to navigate through the menu items.

NOTE: To view each selection, first press the Enter key, and then press the or arrow key to scroll through each selection The HAVPro uses the following reference values to display acceleration, velocity and displacement in dB units:

- Acceleration 10⁻⁶ m/s²
- Velocity 10⁻⁹ m/s,
- Displacement 10⁻¹² m

The following reference values are also available for the user to select:


- Acceleration 10⁻⁵ m/s²
- Velocity 10⁻⁸ m/s
- Displacement 10⁻¹¹ m

dB re $10e-5 \text{ m/s}^2$

5

Printing

The **PRINT** key is the most efficient method for downloading data from the HAVPro. Pressing the **PRINT** key will cause the HAVPro to stream formatted ASCII text to the instrument's serial port connector.



NOTE: The print key only works if you are currently in the History or Data menu.

Only the current data in the HAVPro can be printed. To print a stored data file, first recall the data file from memory using the recall key, and then go through the printing process. To print, use the cable 72-006 computer cable-HAVPro.Using this cable, the HAVPro works with Quest's software package QuestSuitTM Professional for WindowsTM.

Printing to a Windows Hyperterminal


Another option for retrieving data from your HAVPro is printing to a Windows hyperterminal connection. Hyperterminal is a Windows application that is included with Windows. This is an optional installation item, and may not have been installed if a custom installation of Windows was performed. This option will allow you to print the text into the Hyperterminal screen, and then cut and paste text into a word processing or spreadsheet application.

To print to a Hyperterminal connection:


- **Step 1** Collect the data in the HAVPro.
- **Step 2** Use the Print History setting (located in the Tools menu), to select whether or not to include Time History data in the printed report.
- **Step 3** Connect 72-006 to the I/O port on the HAVPro, and to the communications port on your computer.




Step 4 Locate Hyperterminal on your computer. Hyperterminal is usually found in the Start menu, under Programs, and in the Accessories folder.




Step 5 Select Hyperterminal from the menu. A new connection dialog box will appear.



Step 6 Enter a name, and choose an icon for your Hyperterminal connection.



Step 7 Press the OK button.



Step 8 The Connect to dialog box will appear.




Step 9 Select the Com port you will use to communicate with the HAVPro. Press **OK**.

- Step 10 The Communications properties screen will appear as shown below. Select the Baud rate (bits per second) that matches the baud rate on your HAVPro. The other settings are:
- Data bits: 8
- Parity: None

• Stop Bits: 1

• Flow Control: Hardware

.





Press the **OK** button.

You have now established a connection for the HAVPro. You will notice that in the lower left corner of the Hyperterminal screen it states that there is a connection, and will show how long the connection has been in place.




.Left click the **Properties** button





Left click the **Settings Tab** at the top of the window to open the **Setting** dialog box.




Configure the items as shown above and click **ASCI Setup** to open the ASCI Idialog box.




Configure the items as shown above and press **OK** to close the ASCII dialog box..


Press **OK** to close the **Properties** window.

Left click **Transfer** box which will open the following dialog box..




Highlight Capture Text and left click.






Use the Browse function to identify the file into which you want the data transfered and press **Start**.

After the connection has been established, press the **PRINT** key on the HAVPro








and left click.

The data can now be found as a Test file in the folder designated for saving the transferred file.



6

Storing and Recalling Data Files and Setups

This chapter will describe the process of storing data and setup information in the HAVPro's internal memory.

STORE Key

The **STORE** key on the HAVPro has two functions. It will allow you to store data files, and setups. The functionality is determined by the menu you are currently viewing. If you press the store key while you are viewing the Data or History menu, you will be prompted to store a file. If you press the **STORE** key while you are in the Setup, Range, or Tools menu, you will be prompted to store a setup.

Storing a Setup


The power-on default is S0.

To store a setup,

Step 1 Enter the Setup, Tools or Range menu by pressing the **SETUP**, **RANGE** or **TOOLS** key.

Accelerometer ICP

Step 2 Press the **STORE** key.



Step 3 The display will prompt you to store a setup. The flashing number in the lower right corner is referring to the setup register you are currently selecting.




NOTE: To purge all setup registers, go to the Tools menu, use the and arrow keys to select the Erase Setups selection. Press the Enter key, use the arrow key to change the selection to Yes, and press the Enter key again.

Step 4 Select a setup register by pressing the **△** and **▽** arrow keys until the desired selection appears.



Step 5 Press the € arrow key to scroll to the naming section of the screen. You can now enter a name for the setup. Use the € and ▼ arrows to select characters for the positions and the ▶ and € arrow keys to move to the different positions.





Step 6 Press the Enter key. This will store the setup in the selected register and then place you back into the menu from which you started.

To recall a setup from the setup register, see the next section in this manual on the **RECALL** key.

To store a data file,

Step 1 Press the **DATA** or **HISTORY** keys to enter a screen where data is being displayed.





Step 3 The Store File screen will appear. The number in the bottom right of the screen is referring to the file register where the data will be stored.



Step 4 Use the **△** and **▼** arrow keys to select the desired file register.



Step 5 Press the ⓐ arrow key to scroll over to the naming section of the screen. You can now enter a name for the data file. Use the ⓐ and ⑤ arrows to select characters for the positions and the ⑥ and ⑥ arrow keys to move to the different positions.



NOTE: To purge all data files, go to the Tools menu, use the and arrow keys to select the Erase All Files selection. Press the Enter key, use the arrow key to change the selection to Yes, and press the Enter key again.

Step 6 Press the Enter key. The current data has now been stored in the selected register. The data file will also contain all of the setup information that corresponds to that data file. When the data file is recalled, all of the setup information can also be viewed. The data can now be reset, and the stored data will not be lost.

To recall a data file into the current memory, see the next section on the **RECALL** key.

Temporary Data Storage - File Register 00

File register 00 is normally used as a temporary data storage location. For example, if there is un-stored data in the HAVPro and the off key is pressed, the following screen will appear.



Select "No" to turn off the HAVPro without saving. Select "Abort" to cancel the request to turn off. Select "Yes" to store the HAVPro's current data and setup in file register 00, and then turn off.

Once all files have been purged (see chapter 3, Tools Menu), automatic and manual storing of files begins with file register 01. For example, if all files have been purged and there is data in the HAVPro, pressing the **DATA** key, followed by the **STORE** key, will cause the following screen will appear (note, the file register shown will be 01).



If all files have been purged, and the Auto Store feature is enabled (see chapter 2, Getting Started), the HAVPro will automatically store the first file in file register 01. The second file will be automatically stored in file register 02 and so on until all 99 file registers are full.

Preserving the File Counter At Power-Off

The file counter, which keeps track of the last file register used, is saved when the HAVPro is turned off. For example, suppose you store 10 files in file registers 01 thru 10. Then, you turn off the HAVPro. When the HAVPro is turned on again, if you try to store data, the HAVPro will prompt you to store data in file register 11, which is the next empty file register (see screen below).



A separate counter is used when you recall files. For example, suppose you recall and view files 01 thru 05. Then, you turn off the HAVPro. When the HAVPro is turned on again, if you try to recall a file, the HAVPro will prompt you to recall file register 06, which is the next available file to view (see screen below).

Recall File 06

Recall Key


In order to use a setup, or to print a stored file they must be recalled into the current memory of the HAVPro. The **RECALL** key is again dependent on the menu being viewed when the key is pressed. If you are in the Tools, Setup or Range menu and press the **RECALL** key, you will be prompted to recall a setup. If you are in the Data or History menus you will be prompted to recall a data file.


Recalling a Setup

To recall a setup,

Step 1 Enter one of the three valid menus for recalling a setup. The Range menu, the Setup menu, or the Tools menu.







Step 3 You will now be prompted to recall a setup.



Step 4 Use the ▲ and ▼ arrow keys to scroll through the setups until the desired setup appears on the screen.

Recall	Setup	
Wilson	Proses	S 3

Step 5 Press the Enter key to recall the setup.

Recalling Setup Register S0 at Power-On

Setup register S0 is defined as the HAVPro's boot setup. In other words, whenever the HAVPro is turned on, it will automatically recall setup register S0. Therefore, you can configure your HAVPro as desired, save the setup to register S0, and the HAVPro will automatically recall that setup every time the HAVPro is turned on.


If for some reason, the HAVPro needs to be reset to its original factory default settings, the user can erase all setup registers (see chapter 3, Tools Menu). This will reset all setups, including setup register S0, to their factory defaults.

Recalling a File

To recall a stored data file,

Step 1 Press the **DATA** or **HISTORY** key to enter the Data or History menu.

Step 2 Press the **RECALL** Key on the HAVPro.



Recall Key -

Step 3 The screen will prompt you to recall a file.



Step 4 Use the ▲ and ♥ arrow keys to move to the desired selection.



Step 5 Press the Enter key to recall the file into the current memory. All setup information was stored when the data file was stored. That setup information is recalled with the data file, and can be reviewed.

7

Taking Measurements/ Viewing Data on the HAVPro

This chapter will describe how to take a measurement and view the data on the display of the HAVPro.


Run/Stop Key

The Run/Stop key is used to start and stop the measurement. There are several screen indicators that will appear as this key is pressed.

Screen Symbol	Definition
	Run Indicator. Also indicates the level of the input signal coming into the HAVPro. The bar graph is drawn in approximately 5 dB steps.
?	Under Range Indicator.
	Stop Indicator. Indicates that the HAVPro is not running.
*	Latching Overload Indicator.
!	Run - Interrupted Indicator
В	Flashing B indicates a low battery condition.

When an overload occurs on the HAVPro the meter will perform three functions for the overloaded channel.

 The HAVPro indicates when an overload is currently occurring on any of the three inputs. The HAVPro flashes the following screen.



 The HAVPro uses an * to indicate that an overload has occurred since the last reset. The * is displayed on all channels regardless of which channel was overloaded. The Amp value on the overload channel will display "OVER"



 Short Term values like Arms, Peak, Time History values etc. will be reported as OVER whenever an overload corrupts these values.



Under-Range Indicator (?)

The under-range indicator will replace the bar graph run indicator whenever the channel currently displayed is underrange. The under-range indicator, like the bar graph, is independent for all three channels. A channel is under range whenever the input rms signal level is below the minimum RMS Range level as specified in the Typical Measurement Range tables in Appendix A. For example, with 0 dB gain, if the input rms level drops below 74 dB μ V (5 mV), the underrange indicator will be displayed.

Run-Interrupted Indicator (!)

If the HAVPro is stopped and then run again without resetting the current data, the run-interrupted indicator (!) will replace the colon (:) in all displays that show the run time. The "!" indicates that the data in the HAVPro is not contiguous. In other words, the instrument was stopped one or more times during the collection of the data. An example of a data display with the "!" indicator is shown below.

Aeq 0!23!48 1.5000 m/s² Fa2

History Key

NOTE: To view each selection, first press the Enter key, and then press the a or arrow key to scroll through each selection.

NOTE: The 2nd History setting (located in the Setup menu), controls whether or not the Peak levels are stored in the Time History.

The HAVPro will store a time history based on the sample time selected. The Time History buffer has 240 entries available for storage. If you select to store the Peak values as well as the RMS values, the number of time history records is cut in half to 120.

Example:


You have selected an Averaging time of Slow. This Averaging time selected is the one second exponential detector, and if the 2nd History selection in the Setup menu is set to none, you will be able to store for 240 seconds. After 240 seconds the history will start erasing the data from the beginning of the Time History buffer to make room for the incoming data. If the 2nd History selection is set to Peak, then you will have 120 seconds of storage time, and after that, the Time History buffer will begin to erase from the beginning to make room for the new data.

The **HISTORY** key works much the same as the other menus in the HAVPro. To view the Time History data, press the **HISTORY** key.

History Key



You will now be presented with the history data from the first history record. The data is presented in the following format:



Use the $ext{ } ext{ } ext$



Arms
$$0:00:03$$

.01900 m/s² FaZ





```
Arms 0:00:01
.01900 m/s<sup>2</sup> FaZ
```

Viewing Time History with 2nd History turned on

If the 2nd history selection is turned on, the History buffer will alternate between RMS and Peak values for each record.



Arms
$$0:00:02$$

1.5000 m/s² FaZ





```
Arms 0:00:01
1.5000 m/s<sup>2</sup> FaZ
```

Data Key

NOTE: To view each selection, first press the Enter key, and then press the ▶ ♠ or ▼ arrow key to scroll through each selection. The **DATA** key is used to view the overall data being gathered by the instrument. There are 8 screens available in the data menu. To scroll through the menu, use the and arrow keys. To view other channels use the and arrow keys. The screens are formatted as follows.

Data Presented	Screen appearing on the HAVPro
Top screen reports Time and Date. It will also report the last recalled setup, or data file name, which ever was more recent.	Process Batch 03 19:34 03 Oct 99
2nd screen reports detector and averaging time on first line. RMS level, units, frequency weighting and channel on second line. (A=acceleration.)	Arms 10 sec 3.5700 m/s ² FaZ
3rd screen reports minimum level on first line, and maximum level on second line. Frequency weighting and channel are also reported.	Amin .00000 Amax .01430 FaZ
4th screen reports Peak level on first line and the long term maximum peak level on the second line. Frequency weighting and channel are also reported.	Peak .04780 Amp .09550 FaZ
5th screen reports the long term average that runs from run to reset and averaging time on first line. Value, units, frequency weighting and channel on the second line.	Aeq 0:00:01 03 1.5000 m/s ² FaZ

Additional Data view screens for Hand Arm Mode		
The 6th and 7th screens report the Energy Equivalent levels averaged over the run time. 1, 2, 4, and 8 refer to the run time in Hours. (A (8) is the Energy Equivalent level projected over 8 hours)	A(1) .00104 A(2) .00073	FaZ

Additional Data view screens for Hand Arm Mode	
The Frequency weighting and channel are also reported.	A(4) .00052 A(8) .00036 FaZ
The 8th screen shows the Allowed Exposure Time based on the measured $A(8)$ value and a criterion level of 2.8 m/s ² .	A(8) Exposure 3.7 hrs FaZ

Additional Data view screens for Whole Body Mode	
The Vibration Dose Value and run time are displayed on the first line. The value, units, frequency weighting, and channel are displayed on the second line.	VDV 0:00:00 2.9700 m/s ^{7/4} WBZ
Short Term Crest Factor is shown on the first line, the Long Term Crest factor is reported on the second line. The Frequency weighting and channel are also reported.	CF 20.3dB CFmp 0.0dB WBZ

NOTE: The vibration dose value (VDV), specified by ISO 8041 and calculated by the HAVPro, has units of m/s^{7/4}. The HAVPro is also capable of displaying VDV in cm/s^{7/4}, ft/s^{7/4}, or in/s^{7/4} (using the Display Units parameter). However, if Display Units are set to "g" or "dB", the VDV becomes an undefined quantity. Therefore, if the display units are "g" or "dB", the HAVPro will display a series of dashes (-----) for the value.

Please see the specifications appendix for further information regarding specifics of all measured values.

NOTE: The Short-Term Crest factor (CF) is not calculated if the Averaging Time setting is SLOW



Powering the HAVPro

Batteries

The HAVPro operates on 2 AA batteries. See Appendix A for information on typical battery life.

Checking the Remaining Battery Voltage

The battery voltage can be viewed from the data menu by pressing the Enter key. The following screen will be displayed.

Installing New Batteries

To install new batteries in the HAVPro,

Step 1 Remove battery cover from the side of the case.



Step 2 Remove old batteries.



Step 3 Arrange new batteries according to diagram on the inside of the case. Make sure polarity of the batteries is correct.




Step 4 Gently push the new batteries in the case while pushing the battery cover over the battery opening.




Using External Power


The HAVPro can also operate on 7 to 30 Volts DC external power. The external power connector is on the top of the HAVPro.



The power supply normally used with the HAVPro is the Quest Technologies 72-009. This is a switching power supply that will operate on 90 to 260 Volts AC, returning 12 Volts DC.

The connector pinout is as follows:









Connections on the HAVPro

There are 4 connectors located on the outside case of the HAVPro. The Serial Port, input connector, external power connector, and AD/DC Output connector.






The serial port is used for communicating with the HAVPro. The serial port also provides the printer connection.

Pinout

The pinout is as follows,



Pin Num- ber	Description	
1 - RTS	Request To Send	
2 - CTS	Clear To Send	
3 - TXD	Transmit Data	
4 - Ground	Signal Ground	
5 - RXD	Receive Data	
6 - Ground	Signal Ground	
7 - N/C	No Connection	
8 - N/C	No Connection	
The shell of the connector is connected to the Case Shield Ground		


Cables Used

The 72-006-HAVPro is the cable used with the HAVPro. This is a serial connection cable used with Quest's software package QuestSuiteTM Professional for WiindowsTM and also when printing to a Hyperterminal connection.

Transducer Connection

The transducer connection is the input connection into the HAVPro. It is located on the top of the HAVPro case. The connector used is a standard 4-pin LEMOTM connector.

Pinout






Pin#	Description
1	Z - Axis input
2	Y - Axis input
3	X - Axis input
4	Ground


External Power Connection

The HAVPro can also operate on 7 to 30 Volts DC external power. The external power connector is on the top of the HAVPro.

Pinout

The connector pinout is as follows:






Quest Technologies Adapter

The power supply normally used with the HAVPro is the Quest Technologies Adaptor 72-009. This is a switching power supply that will operate on 90 to 260 Volts AC, returning 12 Volts DC.

AC output is useful for frequency analysis by an external analyzer or for recording in a tape recorder. The DC output is useful for a chart recorder, or to measure the voltage proportional to the RMS or peak value.


The DC output is updated according to the averaging time. If the averaging time is set to slow, the signal on the DC output pin for the selected channel will be updated once per second. If the averaging time is set to 60 seconds, the signal on the DC output pin for the selected channel will be updated once every 60 seconds.



The AC output will produce a signal from 0 - 0.5 Volt RMS.

The scale of the DC output is typically 5 mV/dB. The level typically varies between 0 Vdc to +1.0 Vdc.

The AC/DC output connector is a 5 pin switchcraft connector located on the bottom edge of the instrument. The pinout is as follows:



Pin#	Description
1	Ground
2	X - Axis AC/DC Output
3	Y - Axis AC/DC Output
4	No Connection
5	Z - Axis AC/DC Output

The signal that is output on each pin is selectable for each channel. The selections are the same for each channel. We will list the X channel selections, however the available selections will be the same for all operating modes as well.



Specifications

Specifications are subject to change without notice. Numerical values given are typical. Refer to specific calibration or test results for accurate data on a specific unit.

General Characteristics

Type Precision

The Quest Technologies HAVPro Human Vibration Meter is a Type 1 instrument designed for use in assessing vibration as perceived by human beings. The instrument meets the requirements of ISO 8041:1990(E) including Ammendment 1: 1999(E).

Additionally, the current ISO 8041 standard, and therefore the HAVPro, is compatible with the standards listed below. These standards define methods for the measurement of whole-body and hand-arm vibration.

ISO 2631-1:1997 mechanical vibration and shock --Evaluation of human exposure to whole-body vibration --Part 1: General requirements

ISO 2631-2:1989 Evaluation of human exposure to wholebody vibration -- Part 2: Continuous and shock-induced vibrations in buildings (1 to 80 Hz)

ISO 2631-4:2001 Mechanical vibration and shock -- Evaluation of human exposure to whole-body vibration -- Part 4: Guidelines for the evaluation of the effects of vibration and rotational motion on passenger and crew comfort in fixed-guideway transport systems

ISO 5349-1:2001 Mechanical vibration -- Measurement and evaluation of human exposure to hand-transmitted vibration -- Part 1: General requirements

ISO 5349-2:2001 Mechanical vibration -- Measurement and evaluation of human exposure to hand-transmitted vibration -- Part 2: Practical guidance for measurement at the work-place

Effects of Temperature

The RMS level varies ± 0.5 dB when the complete instrument is tested over the - 10° C to 50° C temperature range. The reference reading, for this test, is taken at 20° C and 36% relative humidity (RH); the input signal is at 79.6 Hz.

Effects of Humidity

The RMS level varies ± 0.5 dB when the complete instrument is tested over the 30% to 90% RH range. This test is performed at 40° C, with an input signal of 79.6 Hz.

Limits of Temperature and Humidity

Permanent damage can occur when stored or operated above 60° C or below -20° C. Condensation of moisture will make readings inaccurate. When condensation dissipates, readings should return to normal.

Effects of Magnetic Fields

The RMS level varies ± 0.5 dB when the complete instrument is tested in an 80 A/m, 60 Hz magnetic field (worst case orientation).

Effects of Mechanical Vibrations

The instrument meets the specifications for susceptibility to vibration in accordance with ISO 8041:1990(E) section 7.1.

Stabilization Time

At power-on, allow the instrument to stabilize, approximately 20 seconds, prior to performing any measurements. When changing from one type of input (Direct/Charge/ICP®) to another or when changing the instruments gain settings, allow 10 seconds of stabilization time prior to performing a new measurement.

Data Storage

- 1/2 Mega Byte Memory
- Capable of storing 100 files and 10 setups

• 2 minute (typical) data retention for clock during battery change

Data Communications

• RS-232 Serial Interface

• Maximum Data Rate: 115,000 bits per second

Digital Display

• 2 line, 32 digit, 7 segment LCD display

• Full ASCII character set

• 0.1 dB resolution

Real-time Clock/Calendar

• Accuracy: 0.02% (-10° C to 50° C)

24 hour clock: hh:mm

• Year 2000 Compliant

Run-time Clock

One second resolution

• Format: hh:mm:ss

• Maximum run time: 99:59:59

Power Supply

• Operates with 2 AA alkaline batteries

• Typically operates for 12 hours (Charge/Direct modes)

 Battery life is reduced to approximately 4 hours when using ICP® accelerometers.

• External Power: 7-30 volts DC

Dimensions/Weight

• Width: 3.25 inches (8.3 cm)

• Length: 6.0 inches (15.2 cm)

• Depth: 1.0 inches (2.5 cm)

• Weight: 9.8 ounces (279 grams) - including batteries

Declaration of Conformity



Quest Technologies Inc. Declares that:

Product Name: Human Vibration Meter

Model: HAVPro

in accordance with the following directives:

89/336/EEC The Electromagnetic Compatibility Directive and its amending directives

has been designed and manufactured to the following specifications:

- EN 50081-1 (1992) Electromagnetic compatibility -Generic emission standard Part 1. Residential, commercial, and light industry.
- EN 50082-2 (1995) Electromagnetic compatibility -Generic immunity standard Part 2. Industrial environment.


Outputs

The output impedance is 475 ohms for all of the Analog AC and Analog DC outputs. For minimal error, use instrument with a greater than 100,000 ohm input impedance when making AC or DC output measurements.


Transducer Electrical Impedance

During electrical testing, the following circuits were used in place of the transducer.


Direct Input



ICP® Input



Charge Input



Mode	Data Buffer Measurements	Time History Buffer Measurements
Vibration	Arms, Amin, Amax, Amp, Peak, Aeq	Arms with optional Peak
Hand Arm	Arms, Amin, Amax, Amp, Peak, Aeq, A(1), A(2), A(4), A(8), A(8) Exposure	Arms with optional Peak
Whole Body	Arms, Amin, Amax, Amp, Peak, Aeq, CFmp, CF, VDV	Arms with optional Peak

Reference Acceleration

The reference acceleration (for displaying data in dB) is 10^{-6} m/s², the user can also select a reference of 10^{-5} m/s² (see section 4-3 of the manual for an explanation of how to select the reference acceleration.)

Reference Calibration Frequency

Operating Mode	Frequency Weighting	Reference Calibration Frequency
Vibration	Fa (0.4 Hz to 100 Hz)	7.96 Hz
	Ws (Severity) Fb (0.4 Hz to 1250 Hz) Fc (6.3 Hz to 1250 Hz)	79.6 Hz

Operating Mode	Frequency Weighting	Reference Calibration Frequency
Hand Arm	Wh	79.6 Hz
Whole Body	WB Wb Wc Wd We Wg Wj Wk	7.96 Hz

Reference Calibration Vibration

The reference calibration vibration is 1 m/s^2

Frequency Weighting Curves

Fa (Flat 0.4 Hz to 100 Hz)

Freq (Hz) Nominal	Freq (Hz) True	Fa dB	Tolerance dB
0.100	0.1000	-24.10	+2/-∞
0.125	0.1259	-20.12	+2/ -∞
0.160	0.1585	-16.19	+2/ -∞
0.200	0.1995	-12.34	+2/ -∞
0.250	0.2512	-8.71	+2/-2
0.315	0.3162	-5.51	+2/-2

Freq (Hz) Nominal	Freq (Hz) True	Fa dB	Tolerance dB
0.400	0.3981	-3.05	+1/-1
0.500	0.5012	-1.48	+1/-1
0.630	0.6310	-0.65	+1/-1
0.800	0.7943	-0.27	+1/-1
1.00	1.000	-0.11	+1/-1
1.25	1.259	-0.04	+1/-1
1.60	1.585	-0.02	+1/-1
2.00	1.995	-0.01	+1/-1
2.50	2.512	0.00	+1/-1
3.15	3.162	0.00	+1/-1
4.00	3.981	0.00	+1/-1
5.00	5.012	0.00	+1/-1
6.30	6.310	0.00	+1/-1
8.00	7.943	0.00	0
10.0	10.00	0.00	+1/-1
12.5	12.59	0.00	+1/-1
16.0	15.85	0.00	+1/-1
20.0	19.95	-0.01	+1/-1
25.0	25.12	-0.02	+1/-1
31.5	31.62	-0.04	+1/-1
40.0	39.81	-0.11	+1/-1
50.0	50.12	-0.27	+1/-1
63.0	63.10	-0.64	+1/-1
80.0	79.43	-1.46	+1/-1
100	100.0	-3.01	+1/-1

Freq (Hz) Nominal	Freq (Hz) True	Fa dB	Tolerance dB
125	125.9	-5.46	+2/-2
160	158.5	-8.64	+2/-2
200	199.5	-12.27	+2/ -∞
250	251.2	-16.11	+2/ -∞
315	316.2	-20.04	+2/ -∞
400	398.1	-24.02	+2/ -∞

Fb (Flat 0.4 Hz to 1260 Hz) Frequency Weighting

Freq (Hz) Nominal	Freq (Hz) True	Fb dB	Tolerance dB
0.100	0.1000	-24.10	+2 / -∞
0.125	0.1259	-20.12	+2 / -∞
0.160	0.1585	-16.19	+2 / -∞
0.200	0.1995	-12.34	+2 / -∞
0.250	0.2512	-8.71	+2 / -2
0.315	0.3162	-5.51	+1 / -1
0.400	0.3981	-3.05	+1 / -1
0.500	0.5012	-1.48	+1 / -1
0.630	0.6310	-0.65	+1 / -1
0.800	0.7943	-0.27	+1 / -1
1.00	1.000	-0.11	+1 / -1
1.25	1.259	-0.04	+1 / -1
1.60	1.585	-0.02	+1 / -1
2.00	1.995	-0.01	+1 / -1
2.50	2.512	0.00	+1 / -1

Freq (Hz) Nominal	Freq (Hz) True	Fb dB	Tolerance dB
3.15	3.162	0.00	+1 / -1
4.00	3.981	0.00	+1 / -1
5.00	5.012	0.00	+1 / -1
6.30	6.310	0.00	+1 / -1
8.00	7.943	0.00	+1 / -1
10.0	10.00	0.00	+1 / -1
12.5	12.59	0.00	+1 / -1
16.0	15.85	0.00	+1 / -1
20.0	19.95	0.00	+1 / -1
25.0	25.12	0.00	+1 / -1
31.5	31.62	0.00	+1 / -1
40.0	39.81	0.00	+1 / -1
50.0	50.12	0.00	+1 / -1
63.0	63.10	0.00	+1 / -1
80.0	79.43	0.00	0
100	100.0	0.00	+1 / -1
125	125.9	0.00	+1 / -1
160	158.5	0.00	+1 / -1
200	199.5	0.00	+1 / -1
250	251.2	-0.01	+1 / -1
315	316.2	-0.02	+1 / -1
400	398.1	-0.04	+1 / -1
500	501.2	-0.11	+1 / -1
630	631.0	-0.27	+1 / -1
800	794.3	-0.64	+1 / -1

Freq (Hz) Nominal	Freq (Hz) True	Fb dB	Tolerance dB
1000	1000	-1.46	+2 / -2
1250	1259	-3.01	+2 / -2
1600	1585	-5.46	+2 / -2
2000	1995	-8.64	+2 / -2
2500	2512	-12.27	+2 / -∞
3150	3162	-16.11	+2 / -∞
4000	3981	-20.04	+2 / -∞
5000	5012	-24.02	+2 / -∞
6300	6310	-28.01	+2 / -∞
8000	7943	-32.00	+2 / -∞
10000	10000	-36.00	+2 / -∞

Fc (Flat 6.3 Hz to 1260 Hz), Wh, and Ws Frequency Weighting.

Freq (Hz) Nominal	Freq (Hz) True	Fc dB	Wh dB	Tolerance dB	Ws dB	Tolerance dB
0.800	0.7943	-36.00	-36.00	+2 / -∞	-76.00	+4 / -∞
1.00	1.000	-32.00	-31.99	+2 / -∞	-68.00	+4 / -∞
1.25	1.259	-28.01	-27.99	+2 / -∞	-60.00	+4 / -∞
1.60	1.585	-24.02	-23.99	+2 / -∞	-52.00	+4 / -∞
2.00	1.995	-20.04	-20.01	+2 / -∞	-44.00	+4 / -∞
2.50	2.512	-16.11	-16.05	+2 / -∞	-36.00	+4 / -4
3.15	3.162	-12.27	-12.18	+2 / -∞	-28.00	+4 / -4
4.00	3.981	-8.64	-8.51	+2 / -2	-19.90	+4 / -4
5.00	5.012	-5.46	-5.27	+2 / -2	-12.20	+4 / -4
6.30	6.310	-3.01	-2.77	+2 / -2	-5.30	+4 / -4

Freq (Hz) Nominal	Freq (Hz) True	Fe dB	Wh dB	Tolerance dB	Ws dB	Tolerance dB
8.00	7.943	-1.46	-1.18	+2 / -2	-1.50	+4 / -4
10.0	10.00	-0.64	-0.43	+1 / -1	0.00	+1 / -2
12.5	12.59	027	-0.38	+1 / -1	0.00	+1 / -2
16.0	15.85	-0.11	-0.96	+1 / -1	0.00	+1 / -2
20.0	19.95	-0.04	-2.14	+1 / -1	0.00	+1 / -1
25.0	25.12	-0.02	-3.78	+1 / -1	0.00	+1 / -1
31.5	31.62	-0.01	-5.69	+1 / -1	0.00	+1 / -1
40.0	39.81	0.00	-7.72	+1 / -1	0.00	+1 / -1
50.0	50.12	0.00	-9.78	+1 / -1	0.00	+1 / -1
63.0	63.10	0.00	-11.83	+1 / -1	0.00	+1 / -1
80.0	79.43	0.00	-13.88	0	0.00	0
100	100.0	0.00	-15.91	+1 / -1	0.00	+1 / -1
125	125.9	0.00	-17.93	+1 / -1	0.00	+1 / -1
160	158.5	0.00	-19.94	+1 / -1	0.00	+1 / -1
200	199.5	0.00	-21.95	+1 / -1	0.00	+1 / -1
250	251.2	-0.01	-23.96	+1 / -1	0.00	+1 / -1
315	316.2	-0.02	-25.98	+1 / -1	0.00	+1 / -1
400	398.1	-0.04	-28.00	+1 / -1	0.00	+1 / -1
500	501.2	-0.11	-30.07	+1 / -1	0.00	+1 / -1
630	631.0	-0.27	-32.23	+1 / -1	0.00	+1 / -2
800	794.3	-0.64	-34.60	+1 / -1	0.00	+1 / -2
1000	1000	-1.46	-37.42	+2 / -2	0.00	+1 / -2
1250	1259	-3.01	-40.97	+2 / -2	-1.70	+4 / -4
1600	1585	-5.46	-45.42	+2 / -2	-4.30	+4 / -4
2000	1995	-8.64	-50.60	+2 / -2	-9.80	+4 / -4

Freq (Hz) Nominal	Freq (Hz) True	Fc dB	Wh dB	Tolerance dB	Ws dB	Tolerance dB
2500	2512	-12.27	-56.23	+2 / -∞	-16.30	+4 / -4
3150	3162	-16.11	-62.07	+2 / -∞	-25.80	+4 / -4
4000	3981	-20.04	-68.01	+2 / -∞	-36.00	+4 / -4
5000	5012	-24.02	-73.98	+2 / -∞	-44.00	+4 / -∞
6300	6310	-28.01	-79.97	+2 / -∞	-52.00	+4 / -∞
8000	7943	-32.00	-85.97	+2 / -∞	-60.00	+4 / -∞
10000	10000	-36.00	-91.97	+2 / -∞	-68.00	+4 / -∞

Wb, Wc, and Wd Frequency Weightings

Freq (Hz) Nominal	Freq (Hz) True	Wb dB	Wc dB	Wd dB	Tolerance dB
0.100	0.100	-32.04	-24.10	-24.09	+2 / -∞
0.125	0.1259	-28.20	-20.12	-20.12	+2 / -∞
0.160	0.1585	-23.98	-16.19	-16.18	+2 / -∞
0.200	0.1995	-20.23	-12.34	-12.32	+2 / -∞
0.250	0.2512	-16.71	-8.71	-8.68	+2 / -2
0.315	0.3162	-13.51	-5.51	-5.47	+2 / -2
0.400	0.3981	-10.98	-3.05	-2.98	+1 / -1
0.500	0.5012	-9.53	-1.47	-1.37	+1 / -1
0.630	0.6310	-8.71	-0.64	-0.50	+1 / -1
0.800	0.7943	-8.38	-0.25	-0.08	+1 / -1
1.00	1.00	-8.29	-0.08	+0.10	+1 / -1
1.25	1.259	-8.27	+0.00	+0.06	+1 / -1
1.60	1.585	-8.07	+0.06	-0.26	+1 / -1
2.00	1.995	-7.60	+0.10	-1.00	+1 / -1

Freq (Hz) Nominal	Freq (Hz) True	Wb dB	Wc dB	Wd dB	Tolerance dB
2.50	2.512	-6.13	+0.15	-2.23	+1 / -1
3.15	3.162	-3.58	+0.19	-3.88	+1 / -1
4.00	3.981	-1.02	+0.21	-5.78	+1 / -1
5.00	5.012	0.21	+0.11	-7.78	+1 / -1
6.30	6.310	0.46	-0.23	-9.83	+1 / -1
8.00	7.943	0.21	-0.97	-11.87	0
10.0	10.0	-0.23	-2.20	-13.91	+1 / -1
12.5	12.59	-0.85	-3.84	-15.93	+1 / -1
16.0	15.85	-1.83	-5.74	-17.95	+1 / -1
20.0	19.95	-3.00	-7.75	-19.97	+1 / -1
25.0	25.12	-4.44	-9.80	-21.98	+1 / -1
31.5	31.62	-6.16	-11.87	-24.01	+1 / -1
40.0	39.81	-8.11	-13.97	-26.08	+1 / -1
50.0	50.12	-10.09	-16.15	-28.24	+1 / -1
63.0	63.10	-12.43	-18.55	-30.62	+1 / -1
80.0	79.43	-15.34	-21.37	-33.43	+1 / -1
100	100.0	-18.72	-24.94	-36.99	+1 / -1
125	125.9	-23.00	-29.39	-41.43	+2 / -2
160	158.5	-28.56	-34.57	-46.62	+2 / -2
200	199.5	-34.03	-40.20	-52.24	+2 / -∞
250	251.2	-39.69	-46.04	-58.09	+2 / -∞
315	316.2	-45.65	-51.98	-64.02	+2 / -∞
400	398.1	-51.84	-57.95	-70.00	+2 / -∞

We,Wj, and Wk Frequency Weighting

Freq (Hz) Nominal	Freq (Hz) True	We dB	Wj dB	Wk dB	Tolerance dB
0.100	0.100	-24.08	-30.18	-30.11	+2 / -∞
0.125	0.1259	-20.09	-26.20	-26.14	+2 / -∞
0.160	0.1585	-16.14	-22.27	-22.21	+2 / -∞
0.200	0.1995	-12.27	-18.42	-18.37	+2 / -∞
0.250	0.2512	-8.60	-14.79	-14.74	+2 / -2
0.315	0.3162	-5.36	-11.60	-11.55	+2 / -2
0.400	0.3981	-2.86	-9.15	-9.11	+1 / -1
0.500	0.5012	-1.27	-7.58	-7.56	+1 / -1
0.630	0.6310	-0.55	-6.77	-6.77	+1 / -1
0.800	0.7943	-0.52	-6.42	-6.44	+1 / -1
1.00	1.00	-1.11	-6.30	-6.33	+1 / -1
1.25	1.259	-2.29	-6.28	-6.29	+1 / -1
1.60	1.585	-3.91	-6.32	-6.13	+1 / -1
2.00	1.995	-5.80	-6.34	-5.50	+1 / -1
2.50	2.512	-7.81	-6.22	-3.97	+1 / -1
3.15	3.162	-9.85	-5.60	-1.86	+1 / -1
4.00	3.981	-11.89	-4.08	-0.31	+1 / -1
5.00	5.012	-13.93	-1.99	+0.33	+1 / -1
6.30	6.310	-15.95	-0.47	+0.46	+1 / -1
8.00	7.943	-17.97	+0.14	+0.32	0
10.0	10.0	-19.98	+0.26	-0.10	+1 / -1
12.5	12.59	-21.99	+0.22	-0.93	+1 / -1
16.0	15.85	-23.99	+0.16	-2.22	+1 / -1
20.0	19.95	-26.00	+0.10	-3.91	+1 / -1

Freq (Hz) Nominal	Freq (Hz) True	We dB	Wj dB	Wk dB	Tolerance dB
25.0	25.12	-28.01	+0.06	-5.84	+1 / -1
31.5	31.62	-30.04	+0.00	-7.89	+1 / -1
40.0	39.81	-32.11	-0.08	-10.01	+1 / -1
50.0	50.12	-34.26	-0.25	-12.21	+1 / -1
63.0	63.10	-36.64	-0.63	-14.62	+1 / -1
80.0	79.43	-39.46	-1.45	-17.47	+1 / -1
100	100.0	-43.01	-3.01	-21.04	+1 / -1
125	125.9	-47.46	-5.45	-25.50	+2 / -2
160	158.5	-52.64	-8.64	-30.69	+2 / -2
200	199.5	-58.27	-12.26	-36.32	+2 / -∞
250	251.2	-64.11	-16.11	-42.16	+2 / -∞
315	316.2	-70.04	-20.04	-48.10	+2 / -∞
400	398.1	-76.02	-24.02	-54.08	+2 / -∞

Wg Frequency Weighting (Defined in BS6841:1987)

Freq (Hz) Nominal	Freq (Hz) True	Wg dB	Tolerance dB
1.00	1.00	-7.5	+1 / -1
1.25	1.26	-6.0	+1 / -1
1.60	1.59	-4.6	+1 / -1
2.00	2.00	-3.4	+1 / -1
2.50	2.51	-2.2	+1 / -1
3.15	3.16	-0.9	+1 / -1
4.00	3.98	-0.0	+1 / -1

Freq (Hz) Nominal	Freq (Hz) True	Wg dB	Tolerance dB
5.00	5.01	+0.4	+1 / -1
6.30	6.31	+0.1	+1 / -1
8.00	7.94	-1.0	0
10.0	10.00	-2.5	+1 / -1
12.5	12.59	-4.2	+1 / -1
16.0	15.85	-6.3	+1 / -1
20.0	19.95	-8.2	+1 / -1
25.0	25.12	-10.1	+1 / -1
31.5	31.62	-12.1	+1 / -1
40.0	39.81	-14.2	+1 / -1
50.0	50.12	-16.3	+1 / -1
63.0	63.10	-18.7	+1 / -1
80.0	79.43	-21.6	+1 / -1

WB (Whole Body) Frequency Weighting

Freq (Hz) Nominal	Freq (Hz) True	WB dB	Tolerance dB
0.100	0.100	-36.00	+2 / -∞
0.125	0.1259	-32.00	+2 / -∞
0.160	0.1585	-28.01	+2 / -∞
0.200	0.1995	-24.02	+2 / -∞
0.250	0.2512	-20.05	+2 / -∞
0.315	0.3162	-16.12	+2 / -∞

Freq (Hz) Nominal	Freq (Hz) True	WB dB	Tolerance dB
0.400	0.3981	-12.29	+2 / -∞
0.500	0.5012	-8.67	+2 / -2
0.630	0.6310	-5.51	+2 / -2
0.800	0.7943	-3.09	+2 / -2
1.00	1.00	-1.59	+2 / -2
1.25	1.259	-0.85	+1 / -1
1.60	1.585	-0.59	+1 / -1
2.00	1.995	-0.61	+1 / -1
2.50	2.512	-0.82	+1 / -1
3.15	3.162	-1.19	+1 / -1
4.00	3.981	-1.74	+1 / -1
5.00	5.012	-2.50	+1 / -1
6.30	6.310	-3.49	+1 / -1
8.00	7.943	-4.70	0
10.0	10.0	-6.12	+1 / -1
12.5	12.59	-7.71	+1 / -1
16.0	15.85	-9.44	+1 / -1
20.0	19.95	-11.25	+1 / -1
25.0	25.12	-13.14	+1 / -1
31.5	31.62	-15.09	+1 / -1
40.0	39.81	-17.10	+1 / -1
50.0	50.12	-19.23	+1 / -1
63.0	63.10	-21.58	+1 / -1
80.0	79.43	-24.38	+2 / -2
100	100.0	-27.93	+2 / -2

Freq (Hz) Nominal	Freq (Hz) True	WB dB	Tolerance dB
125	125.9	-32.37	+2 / -2
160	158.5	-37.55	+2 / -2
200	199.5	-43.18	+2 / -∞
250	251.2	-49.02	+2 / -∞
315	316.2	-54.95	+2 / -∞
400	398.1	-60.92	+2 / -∞
500	501.2	-66.91	+2 / -∞
630	631.0	-72.91	+2 / -∞
800	794.3	-78.91	+2 / -∞

Typical Measurements Ranges

Vibration - Fa

	Direct			Charge	Charge (1000pF)			ICP®		
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak	
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range	
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137	
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-17	
40 dB	26	58 dB 36-94	36 dB 61-97	26	58 dB 36-94	36 dB 61-97	26	58 dB 36-94	36 dB 61-97	
60 dB	17	47 dB 27-74	25 dB 52-77	17	47 dB 27-74	25 dB 52-77	23	41 dB 33-74	19 dB 58-77	

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Vibration - Fb, Fc, Ws

	Direct			Charge	Charge (1000pF)			ICP®		
Gain	Noise Floor dBµV	RMS Range dBµV	Peak Range dBµV	Noise Floor dBµV	RMS Range dBµV	Peak Range dBµV	Noise Floor dBµV	RMS Range dBµV	Peak Range dBµV	
0 dB	64	60 dB 74-134	38 dB 99-137	64	60 dB 74-134	38 dB 99-137	64	60 dB 74-134	38 dB 99-137	
20 dB	44	60 dB 54-114	38 dB 79-117	44	60 dB 54-114	38 dB 79-117	44	60 dB 54-114	38 dB 79-117	
40 dB	30	54 dB 40-94	32 dB 65-97	30	54 dB 40-94	32 dB 65-97	30	54 dB 40-94	32 dB 65-97	
60 dB	23	41 dB 33-74	19 dB 58-77	23	41 dB 33-74	19 dB 58-77	23	41 dB 33-74	19 dB 58-77	

Notes

1. The data in the above table was obtained by electrically testing the HAVPro.

Hand Arm - Wh

	Direct			Charge	Charge (1000pF)			ICP®		
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak	
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range	
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137	
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117	
40 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	34-94	59-97	Note 1	34-94	59-97	Note 1	34-94	59-97	
60 dB	10	54 dB 20-74	32 dB 45-77	10	54 dB 20-74	32 dB 45-77	10	54 dB 20-74	32 dB 45-77	

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Whole Body - WB

	Direct			Charge	Charge (1000pF)			ICP®		
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak	
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range	
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137	
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117	
40 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	34-94	59-97	Note 1	34-94	59-97	Note 1	34-94	59-97	
60 dB	14	50 dB 24-74	28 dB 49-77	14	50 dB 24-74	28 dB 49-77	14	50 dB 24-74	28 dB 49-77	

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Whole Body - Wc

	Direct			Charge	Charge (1000pF)			ICP®		
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak	
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range	
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137	
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117	
40 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB	
	Note 1	34-94	59-97	Note 1	34-94	59-97	Note 1	34-94	59-97	
60 dB	13	51 dB 23-74	29 dB 48-77	13	51 dB 23-74	29 dB 48-77	23	41 dB 33-74	19 dB 58-77	

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Whole Body - Wd, We

	Direct		Charge (1000pF)			ICP®			
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117
40 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	34-94	59-97	Note 1	34-94	59-97	Note 1	34-94	59-97
60 dB	11	53 dB 21-74	31 dB 46-77	11	53 dB 21-74	31 dB 46-77	23	41 dB 33-74	19 dB 58-77

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Whole Body - Wg

	Direct		Charge (1000pF)			ICP®			
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117
40 dB	24	60 dB 34-94	38 dB 59-97	24	60 dB 34-94	38 dB 59-97	24	60 dB 34-94	38 dB 59-97
60 dB	14	50 dB 24-74	28 dB 49-77	14	50 dB 24-74	28 dB 49-77	14	50 dB 24-74	28 dB 49-77

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Whole Body - Wb, Wj, Wk

	Direct		Charge (1000pF)			ICP®			
Gain	Noise	RMS	Peak	Noise	RMS	Peak	Noise	RMS	Peak
	Floor	Range	Range	Floor	Range	Range	Floor	Range	Range
	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV	dBµV
0 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	74-134	99-137	Note 1	74-134	99-137	Note 1	74-134	99-137
20 dB	See	60 dB	38 dB	See	60 dB	38 dB	See	60 dB	38 dB
	Note 1	54-114	79-117	Note 1	54-114	79-117	Note 1	54-114	79-117
40 dB	24	60 dB 34-94	38 dB 59-97	24	60 dB 34-94	38 dB 59-97	24	60 dB 34-94	38 dB 59-97
60 dB	13	51 dB 23-74	29 dB 48-77	13	51 dB 23-74	29 dB 48-77	18	46 dB 28-74	24 dB 53-77

Notes:

- 1. Under-Range (?) The noise floor is below the measurement range of the analog to digital converter.
- 2. The data in the above table was obtained by electrically testing the HAVPro.

Trademarks

QuestSuite is a registered trademark of Quest Technologies

PC is a trademark and IBM is a registered trademark of International Business Machines Corporation.

Windows is a registered trademarks of Microsoft Corporation.

ICP® is a registered trademark of the PCB Piezotronics Inc.

B

Glossary

The following appendix contains definitions and explanations of terminology used in the HAVPro

Table of equations

The following table gives many of the calculations the HAVPro performs to arrive at the results reported by the instrument.

Description	Equation
RMS Acceleration	$Aeq = \sqrt{\frac{1}{T} \int_{0}^{T} a_{w}^{2}(t)dt}$
	$T=$ Integration time in seconds. $a_w(t)=$ instantaneous acceleration. $t=$ Time, in seconds.
	The Aeq integration time is from Run to Reset; the display is updated once per second.
RMS Acceleration in Decibels	$Aeq = 20Log \sqrt{\frac{1}{T} \int_{0}^{T} \frac{a_{w}^{2}(t)}{a_{o}^{2}} (dt)} dB$ $a_{o} = \text{reference acceleration, } 10^{-6} \text{ m/s}^{2} \text{ or } 10^{-5} \text{ m/s}^{2} \text{ (user selectable)}$

5/2/03 B-1

Description	Equation
Allowed Exposure Time	$[(2.8m/s^2)/(Aeq)]^2 \times 8hours$
Energy Equivalent RMS Acceleration	The HAVPro measures the following quantities: $A(8) = \sqrt{\frac{1}{8Hours}} \int_{0}^{T} a_{w}^{2}(t)dt$ $A(4) = \sqrt{\frac{1}{4Hours}} \int_{0}^{T} a_{w}^{2}(t)dt$ $A(2) = \sqrt{\frac{1}{2Hours}} \int_{0}^{T} a_{w}^{2}(t)dt$ $A(1) = \sqrt{\frac{1}{1Hours}} \int_{0}^{T} a_{w}^{2}(t)dt$
Running RMS Acceleration LINEAR	$Arms = \sqrt{\frac{1}{\tau} \int_0^t a_w^2(t) dt}$ $\tau = \text{Integration time, in seconds.}$ $t_o = \text{Observation time}$ The linear Arms integration time is controlled by the Averaging time setting; a new linear Arms value is calculated and displayed at the end of each integration period.

Description	Equation
Running RMS Acceleration EXPONENTIAL	$Arms = \sqrt{\frac{1}{\tau} \int_{-\infty}^{\tau_0} a_w^2(t) \exp\left(\frac{t-t_0}{\tau}\right) dt}$
	τ = Time constant of the measurement.
	An averaging time of SLOW is equivalent to a time constant of 1 second.
Vibration Dose Value	$VDV = \left(\int_{0}^{T} a_{w}^{4}(t)dt\right)^{\frac{1}{4}}$
	The <i>VDV</i> integration time is from Run to Reset; the display is updated once per second. The <i>VDV</i> is not calculated for units of dB or g.
Maximum Transient Vibration Value	Amax = maximum reading of all Arms readings from Run to Reset.
	The display is updated at the end of each Averaging time period.
Minimum Transient Vibration Value	Amin = minimum reading of all Arms readings from Run to Reset.
	The display is updated at the end of each Averaging time period.
Long Term Maximum Peak	Amp = peak level of the instantaneous weighted acceleration, $a_w(t)$; measured over the entire measurement period, from Run to Reset.
	The displayed Amp value is updated once per second.

5/2/03 B -3

Description	Equation
Short Term Maximum Peak	Peak = peak level of the instantaneous weighted acceleration, $a_w(t)$; measured during one Averaging time period.
	The peak measurement period is controlled by the Averaging time setting; a new Peak value is calculated and displayed at the end of each Averaging time period.
Long Term Crest Factor	$CFmp = \frac{Amp}{Aeq}$
	The <i>CFmp</i> measurement period is from Run to Reset; the display is updated once per second.
Short Term Crest Factor	$CF = \frac{Peak}{Arms}$ The <i>CF</i> measurement period is controlled by the Averaging time setting; a new <i>CF</i> value is calculated and displayed at the end of each Averaging time period. <i>CF</i> is not calculated if the Averaging time setting is SLOW.
Summed Instantaneous Acceleration	$\sqrt{\left[K_{\chi}a_{W\chi}(t)\right]^2 + \left[K_{\chi}a_{W\chi}(t)\right]^2 + \left[K_{\chi}a_{W\chi}(t)\right]^2 + \left[K_{\chi}a_{W\chi}(t)\right]^2}$ $a_{W\Sigma}(t)$ = instantaneous, summed acceleration $a_{W\chi}(t)$, $a_{W\chi}(t)$, $a_{W\chi}(t)$ = X, Y, and Z axis instantaneous acceleration K_{χ} , K_{χ} , K_{χ} = X, Y, and Z axis Sum Factors The HAVPro uses the formula above to calculate the instantaneous, summed acceleration, $a_{W\Sigma}(t)$. This value is then used to calculate a sum quantity for the A_{rms} , A_{eq} , Peak, VDV, and other metrics.



Serial Interface Commands

The HAVPro is equipped with a serial port for communications with any standard RS-232 device. The most common use for this interface would be to either print, or to create a custom software program that can interface with the HAVPro. The following is a list of commands and their descriptions to assist a programmer in communicating with the HAVPro.

Setup and Query Commands

The setup/query commands are used to control the settings and query the status of the HAVPro parameters. The first 20 commands (S1 - S19, and Q1 - Q19) are reserved for system parameters. System parameter settings remain the same regardless of the operating mode. The remaining commands (S20 - S99, and Q20 - Q99) are for mode specific parameters. Mode specific parameters selections can vary based on the selected operating mode.

Setup commands can be sent at any time. If the HAVPro is running, and changing the parameter requires a reset, then the setup command will cause the instrument to automatically stop, reset, change the parameter setting and start running again. Query commands do not require a stop and reset of the HAVPro.

Syntax for setup commands

The syntax for a setup command is Snn,i. The nn specifies the number of the parameter and 'i' is the desired setting.

The HAVPro returns an 'OK' for valid setup commands and 'NA' for invalid commands.

Syntax for Query commands

The syntax for a query command is Qnn. The nn specifies the parameter to be queried. The HAVPro responds to a query command by returning the current setting of the parameter. For indexed parameters (i.e. parameters for which there is a specific set of choices) the HAVPro returns the index number (i.e. 0, 1, 2, etc.). For alphanumeric parameters the HAVPro returns an ASCII string.

System Parameters (Q's and S's)

The following parameters are independent of the selected operating mode.

Command	Parameter	Setting
S0,yy	Date: Year	yy (00 to 99, 99 = 1999, 00 = 2000, 98 = 2098)
S1,mm	Date: Month	mm (01 to 12)
S2, dd	Date: Day	dd (01 to 31)
S3, hh	Time: Hour	hh (00 to 23)
S4, mm	Time: Minute	mm (00 to 59)
S5, ss	Time: Second	ss (00 to 59)
S6,	Report Header 0	= 1 to 16 characters
S7,	Report Header 1	= 1 to 16 characters

Command	Parameter	Setting
S8,	Report Header 2	= 1 to 16 characters
S9, i	Baud Rate	i = 0 to 3
		0 = 2400
		1 = 9600
		2 = 38.4k
		3 = 115.2k
		NOTE: The baud rate change takes effect immediately after the "OK" response from the HAVPro

Mode Specific Parameters

The following parameters are dependent on which operating mode is selected:

Command	Parameter	Vibration	Hand Arm	Whole Body
S20, i	Operating Mode	i = 0 to 2	i = 0 to 2	i = 0 to 2
		0 = Vibration 1 = Hand Arm 2 = Whole Body	0 = Vibration 1 = Hand Arm 2 = Whole Body	0 = Vibration 1 = Hand Arm 2 = Whole Body
S21, i	Detector Rate	i = 0 to 7	i = 0 to 7	i = 0 to 7
		0 = Slow 1 = 1 2 = 2 3 = 5 4 = 10 5 = 20 6 = 30 7 = 60	0 = Slow 1 = 1 2 = 2 3 = 5 4 = 10 5 = 20 6 = 30 7 = 60	0 = Slow 1 = 1 2 = 2 3 = 5 4 = 10 5 = 20 6 = 30 7 = 60

Command	Parameter	Vibration	Hand Arm	Whole Body
S22, i	Gain X	i = 0 to 3	i = 0 to 3	i = 0 to 3
		0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$
S23, i	Gain Y	i = 0 to 3	i = 0 to 3	i = 0 to 3
		0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$
S24, i	Gain Z	i = 0 to 3	i = 0 to 3	i = 0 to 3
		0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$	0 = 0 $1 = 20$ $2 = 40$ $3 = 60$
S25	Reserved			
S26	Reserved			
S27	Reserved			
S28, hh	Store Time: Hour	hh = 00 to 99	hh = 00 to 99	hh = 00 to 99
S29, mm	Store Time: Minute	mm = 01 to 59	mm = 01 to 59	mm = 01 to 59
S30, i	Accelerometer	i = 0 to 2	i = 0 to 2	i = 0 to 2
		0 = Direct 1 = ICP 2 = Charge	0 = Direct 1 = ICP 2 = Charge	0 = Direct 1 = ICP 2 = Charge

Command	Parameter	Vibration	Hand Arm	Whole Body
S31, i	Display Units	i = 0 to 5	i = 0 to 5	i = 0 to 5
		$0 = m/s^{2}$ $1 = cm/s^{2}$ $2 = ft/s^{2}$ $3 = in/s^{2}$ $4 = g$ $5 = dB$	$0 = m/s^{2}$ $1 = cm/s^{2}$ $2 = ft/s^{2}$ $3 = in/s^{2}$ $4 = g$ $5 = dB$	$0 = m/s^{2}$ $1 = cm/s^{2}$ $2 = ft/s^{2}$ $3 = in/s^{2}$ 4 = g 5 = dB
S32, i	Integration	i = 0 to 2	Not Used	Not Used
		0 = None 1 = Single 2 = Double		
S33	Reserved			
S34, nn	Sum Factor Kx	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)
S35, nn	Sum Factor Ky	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)
S36, nn	Sum Factor Kz	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)	nn = 00 to 99 (Stored as tenths, i.e. 23 = 2.3)
S37, i	Weighting X	i = 0 to 3 0 = Ws 1 = Fa 2 = Fb 3 = Fc	Not Used (Only Wh weighting is available.)	i = 5 to 12 5 = WB 6 = Wb 7 = Wc 8 = Wd 9= We 10= Wg 11 = Wj 12 = Wk

Command	Parameter	Vibration	Hand Arm	Whole Body
S38, i	Weighting Y	i = 0 to 3 0 = Ws 1 = Fa 2 = Fb 3 = Fc	Not Used (Only Wh weighting is available.)	i = 5 to 11 5 = WB 6 = Wb 7 = Wc 8 = Wd 9 = We 10 = Wg 11 = Wj 12 = Wk
S39, i	Weighting Z	i = 0 to 3 0 = Ws 1 = Fa 2 = Fb 3 = Fc	Not Used (Only Wh weighting is available.)	i = 5 to 11 5 = WB 6 = Wb 7 = Wc 8 = Wd 9= We 10= Wg 11 = Wj 12 = Wk
S40, i	AC/DC Output X	$i = 0 \text{ to } 9$ $0 = AC: \text{ Weighted}$ $1 = AC: \text{ Bandlimit}$ $2 = DC: \text{ rms}$ $3 = DC: \text{ min}$ $4 = DC: \text{ max}$ $5 = DC: \text{ peak}$ $6 = DC: \text{ rms } \Sigma$ $7 = DC: \text{ min } \Sigma$ $8 = DC: \text{ max } \Sigma$ $9 = DC: \text{ peak } \Sigma$	$i = 0 \text{ to } 9$ $0 = AC: \text{ Weighted}$ $1 = AC: \text{ Bandlimit}$ $2 = DC: \text{ rms}$ $3 = DC: \text{ min}$ $4 = DC: \text{ max}$ $5 = DC: \text{ peak}$ $6 = DC: \text{ rms } \Sigma$ $7 = DC: \text{ min } \Sigma$ $8 = DC: \text{ max } \Sigma$ $9 = DC: \text{ peak } \Sigma$	i = 0 to 9 0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ

Command	Parameter	Vibration	Hand Arm	Whole Body
S41, i	AC/DC Output	i = 0 to 9	i = 0 to 9	i = 0 to 9
		0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ	0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ	0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ
S42, i	AC/DC Output	i = 0 to 9	i = 0 to 9	i = 0 to 9
		0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ	0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ	0 = AC: Weighted 1 = AC: Bandlimit 2 = DC: rms 3 = DC: min 4 = DC: max 5 = DC: peak $6 = DC$: rms Σ $7 = DC$: min Σ $8 = DC$: max Σ $9 = DC$: peak Σ
S43, i	Auto Store	i = 0 to 2	i = 0 to 2	i = 0 to 2
		0 = Off 1 = On 2 = AutoStop	0 = Off 1 = On 2 = AutoStop	0 = Off 1 = On 2 = AutoStop
S44, i	History Value	i = 0 to 1	i = 0 to 1	i = 0 to 1
		0 = None 1 = Peak	0 = None 1 = Peak	0 = None 1 = Peak
S45	Setup/ File Name	= 1 to12 characters	= 1 to12 characters	= 1 to12 characters

Command	Parameter	Vibration	Hand Arm	Whole Body
S46	Sensitivity X Enter command	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.
	as S46,n.nnne±nn	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge
S47	Sensitivity Y Enter command	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.
	as S47,n.nnne±nn	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge
S48	Sensitivity Z Enter command as	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.	n.nnne±nn = Sensitivity of accelerometer.
	S48,n.nnne±nn	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge	Units: mV/g for Direct and ICP. pC/g for Charge
S49	Cal Level Enter command as	n.nnne±nn = Output level of calibrator	n.nnne±nn = Output level of calibrator	n.nnne±nn = Output level of calibrator
	S49,n.nnne±nn	Units are g	Units are g	Units are g
S50, i	Print History	i = 0 to 1	i = 0 to 1	i = 0 to 1
		0 = No 1 = Yes	0 = No 1 = Yes	0 = No 1 = Yes
S51, i	dB reference	i = 0 to 1	i = 0 to 1	i = 0 to 1
		0 = 1e-05 m/s^2 1 = 1e-06 m/s^2	$0 = 1e-05 \text{ m/s}^2$ $1 = 1e-06 \text{ m/s}^2$	0 = 1e-05 m/s^2 1 = 1e-06 m/s^2

Read Data Commands

NOTE: An R1 command returns the following data: Quest Technologies HAVPro nnnnn rev x.xx (nnnnn is the 5 digit serial number and x.xx is the firmware revision). Not to be confused with Rx1, Ry1, Rz1 or Rs1.

The read commands are used to read data from the data buffer. The syntax for a read command is Rcnn. The c indicates which channel to read (X, Y, Z, or S). The nn indicates which data to read.

Hint: The HAVPro always returns data in decibels, referenced to (10^6 m/s^2) .

R Command nn	Vibration	Hand Arm	Whole Body
0	Elapsed Time	Elapsed Time	Elapsed Time
1	Arms	Arms	Arms
2	Amin	Amin	Amin
3	Amax	Amax	Amax
4	PEAK	PEAK	PEAK
5	Amp	Amp	Amp
6	Aeq	Aeq	Aeq
7	Unused	Aeq1	Unused
8	Unused	Aeq2	Unused
9	Unused	Aeq4	Unused
10	Unused	Aeq8	Unused
11	Unused	Unused	VDV
12	Unused	Unused	CF
13	Unused	Unused	CFmp
14	Unused	Allowed Exposure Time	Unused

Read Time History Commands

The read time history commands are used to read data from the time history buffer. The syntax for this command is Hcnnn,i. The c indicates which channel to read (X, Y, Z, or S). The nnn is an index for indicating which sample to read.

Example: nnn = 0 is the last sample stored, nnn = 1, is the next to last sample stored.

The i indicates which data to read (i = 0 for Arms, or i = 1 for Peak). The commands listed in the following table are also available. The date information (H0 - H5) refers to the starting date/time of the first history record.

Hint: The HAVPro always returns data in decibels, referenced to (10^6 m/s^2) .

Command	Parameter	Settings
НО	History: Year	YY (00 to 99, 99 = 1999, 00 = 2000, 98 = 2098)
H1	History: Month	mm (01 to 12)
H2	History: Day	dd (01 to 31)
Н3	History: Hour	hh (00 to 23)
H4	History: Minute	mm (00 to 59)
Н5	History: Second	ss (00 to 59)
Н6	Number of Samples	000 to 239
Н7	Number of Wraps	Returns the number of times the buffer has been completely filled. After the buffer is filled, new data is simply written over the existing data. (i.e. the buffer always contains the last 240 samples, or 120 samples if Peak is also stored.)

Control Commands

Command	Description	Notes					
MO	Status	This command returns 3 ASCII bytes separated by commas (i.e. bye1, byte2, byte3). For example, for a status of 4, 3, 7, the 4 indicates that the currently available data (currently displayed data) is file data. The 4 also indicates that a pause did not occur during the time the data was collected. Finally, the 4 also conveys that the instrument is currently stopped. The 3 indicates that the X and Y channels are currently overloaded. The 7 indicates that the X, Y, Z latching overload indicators are all set. The 3 least significant bits of each byte are used to communmicate status information as shown below. Byte1 xxxxxnnn					
M1	Run	HAVPro returns "OK" for valid command.					
M2	Stop	HAVPro returns "OK" for valid command.					
M3	Reset	HAVPro returns "OK" for valid command.					
M4, n	Store Setup n = 0 to 9	HAVPro will store the current setup in the setup register indicated by n (0 is default). Returns "OK" for valid command.					

Command	Description	Notes
M5, n	Recall Setup n = 0 to 99	HAVPro will recall the setup indicated by n (0 is default). Returns "OK" for valid command.
		Returns "NO" if a setup has never been stored in the nth setup location.
M6, n	Store File n = 0 to 99	HAVPro will store a file in the location specified by n (0 is default). Returns "OK" for valid command.
M7, n	Recall File n = 0 to 99	HAVPro will recall the file specified by n (0 is default). Returns "OK" for valid command.
		Returns "NO" if a file has never been stored in the nth file location.
		Returns "NA" if the file location is not available (i.e. less than 0 or greater than 99).
M8, n	File Empty? n = 0 to 99	HAVPro will respond as to whether or not the file indicated by n (0 is default) is empty $(1 = \text{full}, 0 = \text{empty})$.
M9	Reserved	
M10	Print	HAVPro will print report
M11	Battery	HAVPro returns current battery level (volts)
M12	External Power	HAVPro returns currnet external power level (volts)
M13	Reserved	
M123459	Erase Setups	Erases all setups (HAVPro responds to command by counting down from 9 to 0 while erasing setups), final response is "OK"
M123457	Erase Files	Erases all files (HAVPro responds to command by counting down from 9 to 0 while erasing




Frequency Response Curves

The following are typical frequency response curves for the HAVPro. Specifications are subject to change without notice. Numerical values given are typical. Refer to specific calibration or test results for accurate data on a specific unit.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Fa Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s 2 (dB reference = 1e-6 m/s 2) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Fa weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Fr	eq (Hz)	Theor	Measured	Error	Tolerance
0.10	-24.1	-24.0	+0.1	+1.0, -998.0		7.94	+0.0	+0.0	+0.0	+0.0, +0.0
0.13	-20.1	-21.4	-1.3	+1.0, -998.0		10.00	+0.0	+0.0	+0.0	+0.5, -0.5
0.16	-16.2	-17.1	-0.9	+1.0, -998.0		12.59	+0.0	+0.0	+0.0	+0.5, -0.5
0.20	-12.3	-12.9	-0.6	+1.0, -998.0		15.85	+0.0	+0.0	+0.0	+0.5, -0.5
0.25	-8.7	-9.1	-0.4	+1.0, -1.0	1	19.95	-0.0	+0.0	+0.0	+0.5, -0.5
0.32	-5.5	-5.8	-0.2	+1.0, -1.0	1	25.12	-0.0	-0.1	-0.1	+0.5, -0.5
0.40	-3.0	-3.3	-0.2	+0.5, -0.5	1	31.62	-0.0	-0.1	-0.1	+0.5, -0.5
0.50	-1.5	-1.6	-0.1	+0.5, -0.5	1	39.81	-0.1	-0.2	-0.1	+0.5, -0.5
0.63	-0.6	-0.8	-0.2	+0.5, -0.5	1	50.12	-0.3	-0.3	+0.0	+0.5, -0.5
0.79	-0.3	-0.4	-0.1	+0.5, -0.5	1	63.10	-0.6	-0.7	-0.1	+0.5, -0.5
1.00	-0.1	-0.2	-0.1	+0.5, -0.5	1	79.43	-1.5	-1.5	+0.0	+0.5, -0.5
1.26	-0.0	-0.1	-0.1	+0.5, -0.5	1	100.00	-3.0	-3.0	+0.0	+0.5, -0.5
1.59	-0.0	+0.0	+0.0	+0.5, -0.5	1	125.90	-5.5	-5.4	+0.1	+1.0, -1.0
2.00	-0.0	+0.0	+0.0	+0.5, -0.5	1	158.50	-8.6	-8.5	+0.1	+1.0, -1.0
2.51	+0.0	+0.0	+0.0	+0.5, -0.5	1	199.50	-12.3	-12.1	+0.2	+1.0, -998.
3.16	+0.0	+0.0	+0.0	+0.5, -0.5	1	251.20	-16.1	-15.9	+0.2	+1.0, -998.
3.98	+0.0	-0.1	-0.1	+0.5, -0.5	1	316.20	-20.0	-19.8	+0.2	+1.0, -998.
5.01	+0.0	+0.0	+0.0	+0.5, -0.5	1	398.10	-24.0	-23.8	+0.2	+1.0, -998.
6.31	+0.0	+0.0	+0.0	+0.5, -0.5	1					

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Fb Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Fb weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-24.1	-25.8	-1.6	+1.0, -998.0	39.81	+0.0	+0.0	+0.0	+0.5, -0.5
0.13	-20.1	-21.7	-1.5	+1.0, -998.0	50.12	+0.0	+0.0	+0.0	+0.5, -0.5
0.16	-16.2	-17.2	-1.0	+1.0, -998.0	63.10	+0.0	+0.0	+0.0	+0.5, -0.5
0.20	-12.3	-12.9	-0.5	+1.0, -998.0	79.43	+0.0	+0.0	+0.0	+0.0, +0.0
0.25	-8.7	-9.2	-0.4	+1.0, -1.0	100.00	+0.0	+0.0	+0.0	+0.5, -0.5
0.32	-5.5	-5.8	-0.3	+1.0, -1.0	125.90	+0.0	+0.0	+0.0	+0.5, -0.5
0.40	-3.0	-3.3	-0.2	+0.5, -0.5	158.50	+0.0	+0.0	+0.0	+0.5, -0.5
0.50	-1.5	-1.6	-0.1	+0.5, -0.5	199.50	+0.0	+0.0	+0.0	+0.5, -0.5
0.63	-0.6	-0.8	-0.2	+0.5, -0.5	251.20	-0.0	-0.1	+0.0	+0.5, -0.5
0.79	-0.3	-0.4	-0.1	+0.5, -0.5	316.20	-0.0	-0.1	-0.1	+0.5, -0.5
1.00	-0.1	-0.2	-0.1	+0.5, -0.5	398.10	-0.0	-0.1	-0.1	+0.5, -0.5
1.26	-0.0	-0.1	-0.1	+0.5, -0.5	501.20	-0.1	-0.2	-0.1	+0.5, -0.5
1.59	-0.0	-0.1	-0.1	+0.5, -0.5	631.00	-0.3	-0.4	-0.1	+0.5, -0.5
2.00	-0.0	-0.1	-0.1	+0.5, -0.5	794.30	-0.6	-0.7	-0.1	+0.5, -0.5
2.51	+0.0	+0.0	+0.0	+0.5, -0.5	1000.00	-1.5	-1.5	+0.0	+1.0, -1.0
3.16	+0.0	+0.0	+0.0	+0.5, -0.5	1259.00	-3.0	-2.9	+0.1	+1.0, -1.0
3.98	+0.0	+0.0	+0.0	+0.5, -0.5	1585.00	-5.5	-5.4	+0.1	+1.0, -1.0
5.01	+0.0	+0.0	+0.0	+0.5, -0.5	1995.00	-8.6	-9.0	-0.4	+1.0, -1.0
6.31	+0.0	+0.0	+0.0	+0.5, -0.5	2512.00	-12.3	-14.6	-2.3	+1.0, -998.
7.94	+0.0	+0.0	+0.0	+0.5, -0.5	3162.00	-16.1	-24.2	-8.1	+1.0, -998.
10.00	+0.0	+0.0	+0.0	+0.5, -0.5	3981.00	-20.0	-46.3	-26.3	+1.0, -998
12.59	+0.0	+0.0	+0.0	+0.5, -0.5	5012.00	-24.0	-69.9	-45.9	+1.0, -998.
15.85	+0.0	+0.0	+0.0	+0.5, -0.5	6310.00	-28.0	-71.1	-43.1	+1.0, -998.
19.95	+0.0	+0.0	+0.0	+0.5, -0.5	7943.00	-32.0	-70.9	-38.9	+1.0, -998.
25.12	+0.0	+0.0	+0.0	+0.5, -0.5	10000.00	-36.0	-70.7	-34.7	+1.0, -998.
31.62	+0.0	+0.0	+0.0	+0.50.5	I				

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Fc Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Fc weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.79	-36.0	-36.1	-0.1	+1.0, -998.0	100.00	+0.0	+0.0	+0.0	+0.5, -0.5
1.00	-32.0	-32.1	-0.1	+1.0, -998.0	125.90	+0.0	+0.0	+0.0	+0.5, -0.5
1.26	-28.0	-28.1	-0.1	+1.0, -998.0	158.50	+0.0	+0.0	+0.0	+0.5, -0.5
1.59	-24.0	-24.0	+0.0	+1.0, -998.0	199.50	+0.0	+0.0	+0.0	+0.5, -0.5
2.00	-20.0	-20.1	-0.1	+1.0, -998.0	251.20	-0.0	+0.0	+0.0	+0.5, -0.5
2.51	-16.1	-16.1	+0.0	+1.0, -998.0	316.20	-0.0	-0.1	-0.1	+0.5, -0.5
3.16	-12.3	-12.3	+0.0	+1.0, -998.0	398.10	-0.0	-0.1	-0.1	+0.5, -0.5
3.98	-8.6	-8.7	-0.1	+1.0, -1.0	501.20	-0.1	-0.2	-0.1	+0.5, -0.5
5.01	-5.5	-5.5	+0.0	+1.0, -1.0	631.00	-0.3	-0.3	+0.0	+0.5, -0.5
6.31	-3.0	-3.0	+0.0	+1.0, -1.0	794.30	-0.6	-0.7	-0.1	+0.5, -0.5
7.94	-1.5	-1.5	+0.0	+1.0, -1.0	1000.00	-1.5	-1.5	+0.0	+1.0, -1.0
10.00	-0.6	-0.7	-0.1	+0.5, -0.5	1259.00	-3.0	-2.9	+0.1	+1.0, -1.0
12.59	-0.3	-0.3	+0.0	+0.5, -0.5	1585.00	-5.5	-5.4	+0.1	+1.0, -1.0
15.85	-0.1	-0.1	+0.0	+0.5, -0.5	1995.00	-8.6	-9.0	-0.4	+1.0, -1.0
19.95	-0.0	-0.1	-0.1	+0.5, -0.5	2512.00	-12.3	-14.6	-2.3	+1.0, -998.0
25.12	-0.0	+0.0	+0.0	+0.5, -0.5	3162.00	-16.1	-24.2	-8.1	+1.0, -998.0
31.62	-0.0	+0.0	+0.0	+0.5, -0.5	3981.00	-20.0	-46.3	-26.3	+1.0, -998.0
39.81	+0.0	+0.0	+0.0	+0.5, -0.5	5012.00	-24.0	-69.9	-45.9	+1.0, -998.0
50.12	+0.0	+0.0	+0.0	+0.5, -0.5	6310.00	-28.0	-71.3	-43.2	+1.0, -998.0
63.10	+0.0	+0.0	+0.0	+0.5, -0.5	7943.00	-32.0	-70.8	-38.8	+1.0, -998.0
79.43	+0.0	+0.0	+0.0	+0.0, +0.0	10000.00	-36.0	-70.7	-34.7	+1.0, -998.0

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Wh Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s 2 (dB reference = 1e-6 m/s 2) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wh weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




	• • • •								
Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.79	-36.0	-36.1	-0.1	+1.0, -998.0	100.00	-15.9	-15.9	+0.0	+0.5, -0.5
1.00	-32.0	-32.0	+0.0	+1.0, -998.0	125.90	-17.9	-17.9	+0.0	+0.5, -0.5
1.26	-28.0	-28.1	-0.1	+1.0, -998.0	158.50	-19.9	-19.9	+0.0	+0.5, -0.5
1.59	-24.0	-24.0	+0.0	+1.0, -998.0	199.50	-22.0	-22.0	+0.0	+0.5, -0.5
2.00	-20.0	-20.0	+0.0	+1.0, -998.0	251.20	-24.0	-24.0	+0.0	+0.5, -0.5
2.51	-16.0	-16.1	+0.0	+1.0, -998.0	316.20	-26.0	-26.0	+0.0	+0.5, -0.5
3.16	-12.2	-12.2	+0.0	+1.0, -998.0	398.10	-28.0	-28.0	+0.0	+0.5, -0.5
3.98	-8.5	-8.5	+0.0	+1.0, -1.0	501.20	-30.1	-30.1	+0.0	+0.5, -0.5
5.01	-5.3	-5.3	+0.0	+1.0, -1.0	631.00	-32.2	-32.3	+0.0	+0.5, -0.5
6.31	-2.8	-2.8	+0.0	+1.0, -1.0	794.30	-34.6	-34.6	+0.0	+0.5, -0.5
7.94	-1.2	-1.2	+0.0	+1.0, -1.0	1000.00	-37.4	-37.3	+0.1	+1.0, -1.0
10.00	-0.4	-0.4	+0.0	+0.5, -0.5	1259.00	-41.0	-40.7	+0.3	+1.0, -1.0
12.59	-0.4	-0.4	+0.0	+0.5, -0.5	1585.00	-45.4	-45.1	+0.3	+1.0, -1.0
15.85	-1.0	-1.0	+0.0	+0.5, -0.5	1995.00	-50.6	-50.7	-0.1	+1.0, -1.0
19.95	-2.1	-2.1	+0.1	+0.5, -0.5	2512.00	-56.2	-58.0	-1.7	+1.0, -998.
25.12	-3.8	-3.8	+0.0	+0.5, -0.5	3162.00	-62.1	-69.5	-7.4	+1.0, -998.
31.62	-5.7	-5.7	+0.0	+0.5, -0.5	3981.00	-68.0	-107.3	-39.3	+1.0, -998.
39.81	-7.7	-7.7	+0.0	+0.5, -0.5	5012.00	-74.0	-107.8	-33.8	+1.0, -998.
50.12	-9.8	-9.8	+0.0	+0.5, -0.5	6310.00	-80.0	-104.8	-24.9	+1.0, -998.
63.10	-11.8	-11.8	+0.1	+0.5, -0.5	7943.00	-86.0	-108.0	-22.0	+1.0, -998.
79.43	-13.9	-13.9	+0.0	+0.0, +0.0	10000.00	-92.0	-104.0	-12.1	+1.0, -998

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X WB Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s^2 (dB reference = $1e\text{-}6 \text{ m/s}^2$) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (WB weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-36.0	-37.6	-1.6	+1.0, -998.0	10.00	-6.1	-6.1	+0.0	+0.5, -0.5
0.13	-32.0	-33.4	-1.4	+1.0, -998.0	12.59	-7.7	-7.7	+0.0	+0.5, -0.5
0.16	-28.0	-28.9	-0.9	+1.0, -998.0	15.85	-9.4	-9.5	-0.1	+0.5, -0.5
0.20	-24.0	-24.8	-0.8	+1.0, -998.0	19.95	-11.3	-11.3	-0.1	+0.5, -0.5
0.25	-20.0	-20.5	-0.5	+1.0, -998.0	25.12	-13.1	-13.2	-0.1	+0.5, -0.5
0.32	-16.1	-16.5	-0.4	+1.0, -998.0	31.62	-15.1	-15.1	+0.0	+0.5, -0.5
0.40	-12.3	-12.6	-0.3	+1.0, -998.0	39.81	-17.1	-17.2	-0.1	+0.5, -0.5
0.50	-8.7	-8.9	-0.2	+1.0, -1.0	50.12	-19.2	-19.3	-0.1	+0.5, -0.5
0.63	-5.5	-5.8	-0.2	+1.0, -1.0	63.10	-21.6	-21.6	+0.0	+0.5, -0.5
0.79	-3.1	-3.2	-0.1	+1.0, -1.0	79.43	-24.4	-24.4	+0.0	+1.0, -1.0
1.00	-1.6	-1.7	-0.1	+1.0, -1.0	100.00	-27.9	-27.9	+0.0	+1.0, -1.0
1.26	-0.9	-0.9	-0.1	+0.5, -0.5	125.90	-32.4	-32.3	+0.1	+1.0, -1.0
1.59	-0.6	-0.7	-0.1	+0.5, -0.5	158.50	-37.5	-37.4	+0.1	+1.0, -1.0
2.00	-0.6	-0.7	+0.0	+0.5, -0.5	199.50	-43.2	-43.0	+0.2	+1.0, -998.0
2.51	-0.8	-0.9	-0.1	+0.5, -0.5	251.20	-49.0	-48.7	+0.3	+1.0, -998.0
3.16	-1.2	-1.2	+0.0	+0.5, -0.5	316.20	-55.0	-54.7	+0.2	+1.0, -998.0
3.98	-1.7	-1.8	-0.1	+0.5, -0.5	398.10	-60.9	-60.7	+0.2	+1.0, -998.0
5.01	-2.5	-2.6	-0.1	+0.5, -0.5	501.20	-66.9	-66.7	+0.2	+1.0, -998.0
6.31	-3.5	-3.5	+0.0	+0.5, -0.5	631.00	-72.9	-72.9	+0.0	+1.0, -998.0
7.94	-4.7	-4.7	+0.0	+0.0, +0.0	794.30	-78.9	-80.2	-1.2	+1.0, -998.0

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 **Certificate of X Wb Electrical Conformance**

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wb weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Frequency (Hz)

Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-32.0	-32.2	-0.1	+1.0, -998.0	7.94	+0.2	+0.2	+0.0	+0.0, +0.0
0.13	-28.2	-29.3	-1.1	+1.0, -998.0	10.00	-0.2	-0.3	-0.1	+0.5, -0.5
0.16	-24.0	-25.0	-1.0	+1.0, -998.0	12.59	-0.9	-0.9	+0.0	+0.5, -0.5
0.20	-20.2	-20.8	-0.6	+1.0, -998.0	15.85	-1.8	-1.8	+0.0	+0.5, -0.5
0.25	-16.7	-17.1	-0.4	+1.0, -1.0	19.95	-3.0	-3.0	+0.0	+0.5, -0.5
0.32	-13.5	-13.8	-0.3	+1.0, -1.0	25.12	-4.4	-4.5	+0.0	+0.5, -0.5
0.40	-11.0	-11.3	-0.3	+0.5, -0.5	31.62	-6.2	-6.2	+0.0	+0.5, -0.5
0.50	-9.5	-9.6	-0.1	+0.5, -0.5	39.81	-8.1	-8.1	+0.0	+0.5, -0.5
0.63	-8.7	-8.9	-0.2	+0.5, -0.5	50.12	-10.1	-10.2	-0.1	+0.5, -0.5
0.79	-8.4	-8.5	-0.1	+0.5, -0.5	63.10	-12.4	-12.5	-0.1	+0.5, -0.5
1.00	-8.3	-8.4	-0.1	+0.5, -0.5	79.43	-15.3	-15.2	+0.2	+0.5, -0.5
1.26	-8.3	-8.3	+0.0	+0.5, -0.5	100.00	-18.7	-18.7	+0.0	+0.5, -0.5
1.59	-8.1	-8.2	-0.1	+0.5, -0.5	125.90	-23.0	-23.1	-0.1	+1.0, -1.0
2.00	-7.6	-7.6	+0.0	+0.5, -0.5	158.50	-28.6	-28.2	+0.4	+1.0, -1.0
2.51	-6.1	-6.1	+0.0	+0.5, -0.5	199.50	-34.0	-33.8	+0.2	+1.0, -998.
3.16	-3.6	-3.6	+0.0	+0.5, -0.5	251.20	-39.7	-39.6	+0.1	+1.0, -998.
3.98	-1.0	-1.1	-0.1	+0.5, -0.5	316.20	-45.7	-45.5	+0.2	+1.0, -998.
5.01	+0.2	+0.2	+0.0	+0.5, -0.5	398.10	-51.8	-51.5	+0.4	+1.0, -998.
6.31	+0.5	+0.4	+0.0	+0.5, -0.5	I .				

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 **Certificate of X Wc Electrical Conformance**

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s 2 (dB reference = 1e-6 m/s 2) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wc weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
	-24.1	-24.1	+0.0	+1.0, -998.0	7.94	-1.0	-1.0	+0.0	+0.0, +0.0
0.13	-20.1 -16.2	-21.4 -17.1	-1.3 -0.9	+1.0, -998.0 +1.0, -998.0	10.00 12.59	-2.2 -3.8	-2.2 -3.9	+0.0	+0.5, -0.5 +0.5, -0.5
0.20	-12.3	-12.9	-0.5	+1.0, -998.0	15.85	-5.7	-5.8	+0.0	+0.5, -0.5
0.25	-8.7	-9.2	-0.5	+1.0, -1.0	19.95	-7.8	-7.8	+0.0	+0.5, -0.5
0.32	-5.5	-5.8	-0.3	+1.0, -1.0	25.12	-9.8	-9.8	+0.0	+0.5, -0.5
0.40	-3.0	-3.2	-0.2	+0.5, -0.5	31.62	-11.9	-11.9	+0.0	+0.5, -0.5
0.50	-1.5	-1.6	-0.1	+0.5, -0.5	39.81	-14.0	-14.0	+0.0	+0.5, -0.5
0.63	-0.6	-0.8	-0.1	+0.5, -0.5	50.12	-16.1	-16.2	+0.0	+0.5, -0.5
0.79	-0.3	-0.4	-0.1	+0.5, -0.5	63.10	-18.5	-18.6	+0.0	+0.5, -0.5
1.00	-0.1	-0.2	-0.1	+0.5, -0.5	79.43	-21.4	-21.4	+0.0	+0.5, -0.5
1.26	+0.0	-0.1	-0.1	+0.5, -0.5	100.00	-24.9	-24.9	+0.1	+0.5, -0.5
1.59	+0.1	+0.0	+0.0	+0.5, -0.5	125.90	-29.4	-29.3	+0.1	+1.0, -1.0
2.00	+0.1	+0.0	-0.1	+0.5, -0.5	158.50	-34.6	-34.4	+0.2	+1.0, -1.0
2.51	+0.2	+0.1	+0.0	+0.5, -0.5	199.50	-40.2	-40.0	+0.2	+1.0, -998.0
3.16	+0.2	+0.1	-0.1	+0.5, -0.5	251.20	-46.0	-45.9	+0.2	+1.0, -998.0
3.98	+0.2	+0.2	+0.0	+0.5, -0.5	316.20	-52.0	-51.6	+0.4	+1.0, -998.0
5.01	+0.1	+0.1	+0.0	+0.5, -0.5	398.10	-58.0	-57.7	+0.3	+1.0, -998.0
6.31	-0.2	-0.3	+0.0	+0.5, -0.5					

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Technician: Test Date: Mar 14,2003

Quest Technologies Model: HAVPro; Serial Number: 03001 **Certificate of X Wd Electrical Conformance**

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wd weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-24.1	-24.0	+0.1	+1.0, -998.0	7.94	-11.9	-11.9	+0.0	+0.0, +0.0
0.13	-20.1	-21.4	-1.3	+1.0, -998.0	10.00	-13.9	-13.9	+0.0	+0.5, -0.5
0.16	-16.2	-17.0	-0.8	+1.0, -998.0	12.59	-15.9	-16.0	+0.0	+0.5, -0.5
0.20	-12.3	-12.8	-0.5	+1.0, -998.0	15.85	-18.0	-18.0	+0.0	+0.5, -0.5
0.25	-8.7	-9.1	-0.4	+1.0, -1.0	19.95	-20.0	-20.0	+0.0	+0.5, -0.5
0.32	-5.5	-5.7	-0.2	+1.0, -1.0	25.12	-22.0	-22.0	+0.0	+0.5, -0.5
0.40	-3.0	-3.1	-0.1	+0.5, -0.5	31.62	-24.0	-24.1	-0.1	+0.5, -0.5
0.50	-1.4	-1.5	-0.1	+0.5, -0.5	39.81	-26.1	-26.1	+0.0	+0.5, -0.5
0.63	-0.5	-0.6	-0.1	+0.5, -0.5	50.12	-28.2	-28.3	+0.0	+0.5, -0.5
0.79	-0.1	-0.2	-0.1	+0.5, -0.5	63.10	-30.6	-30.7	+0.0	+0.5, -0.5
1.00	+0.1	+0.0	-0.1	+0.5, -0.5	79.43	-33.4	-33.5	+0.0	+0.5, -0.5
1.26	+0.1	+0.0	+0.0	+0.5, -0.5	100.00	-37.0	-37.0	+0.0	+0.5, -0.5
1.59	-0.3	-0.3	+0.0	+0.5, -0.5	125.90	-41.4	-41.4	+0.1	+1.0, -1.0
2.00	-1.0	-1.0	+0.0	+0.5, -0.5	158.50	-46.6	-46.5	+0.2	+1.0, -1.0
2.51	-2.2	-2.3	+0.0	+0.5, -0.5	199.50	-52.2	-51.9	+0.4	+1.0, -998.0
3.16	-3.9	-3.9	+0.0	+0.5, -0.5	251.20	-58.1	-57.8	+0.3	+1.0, -998.0
3.98	-5.8	-5.8	+0.0	+0.5, -0.5	316.20	-64.0	-63.6	+0.4	+1.0, -998.0
5.01	-7.8	-7.8	+0.0	+0.5, -0.5	398.10	-70.0	-69.8	+0.2	+1.0, -998.0
6.31	-9.8	-9.8	+0.0	+0.5, -0.5	I				

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Technician: Test Date: Mar 14,2003

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X We Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (We weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-24.1	-25.3	-1.2	+1.0, -998.0	7.94	-18.0	-18.0	+0.0	+0.0, +0.0
0.13	-20.1	-21.4	-1.3	+1.0, -998.0	10.00	-20.0	-20.0	+0.0	+0.5, -0.5
0.16	-16.1	-17.1	-0.9	+1.0, -998.0	12.59	-22.0	-22.0	+0.0	+0.5, -0.5
0.20	-12.3	-12.9	-0.6	+1.0, -998.0	15.85	-24.0	-24.0	+0.0	+0.5, -0.5
0.25	-8.6	-9.0	-0.4	+1.0, -1.0	19.95	-26.0	-26.0	+0.0	+0.5, -0.5
0.32	-5.4	-5.6	-0.3	+1.0, -1.0	25.12	-28.0	-28.1	-0.1	+0.5, -0.5
0.40	-2.9	-3.1	-0.2	+0.5, -0.5	31.62	-30.0	-30.1	+0.0	+0.5, -0.5
0.50	-1.3	-1.4	-0.1	+0.5, -0.5	39.81	-32.1	-32.2	-0.1	+0.5, -0.5
0.63	-0.6	-0.7	-0.1	+0.5, -0.5	50.12	-34.3	-34.3	+0.0	+0.5, -0.5
0.79	-0.5	-0.6	-0.1	+0.5, -0.5	63.10	-36.6	-36.7	+0.0	+0.5, -0.5
1.00	-1.1	-1.2	-0.1	+0.5, -0.5	79.43	-39.5	-39.5	+0.0	+0.5, -0.5
1.26	-2.3	-2.3	+0.0	+0.5, -0.5	100.00	-43.0	-43.0	+0.0	+0.5, -0.5
1.59	-3.9	-3.9	+0.0	+0.5, -0.5	125.90	-47.5	-47.4	+0.1	+1.0, -1.0
2.00	-5.8	-5.8	+0.0	+0.5, -0.5	158.50	-52.6	-52.5	+0.2	+1.0, -1.0
2.51	-7.8	-7.9	-0.1	+0.5, -0.5	199.50	-58.3	-58.2	+0.1	+1.0, -998.0
3.16	-9.9	-9.9	+0.0	+0.5, -0.5	251.20	-64.1	-63.5	+0.6	+1.0, -998.0
3.98	-11.9	-11.9	+0.0	+0.5, -0.5	316.20	-70.0	-69.6	+0.5	+1.0, -998.0
5.01	-13.9	-13.9	+0.0	+0.5, -0.5	398.10	-76.0	-75.8	+0.2	+1.0, -998.0
6.31	-15.9	-16.0	+0.0	+0.5, -0.5	I				

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Wg Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wg weighted, 20 dB gain, ICP input) was then electrically tested as specified in BS 6841:1987.




Freq (Hz)	Theor	Measured	Error	Tolerance	1	Freq (Hz)	Theor	Measured	Error	Tolerance
1.00	-7.5	-7.5	+0.0	+0.5, -0.5		10.00	-2.5	-2.5	+0.0	+0.5, -0.5
1.26	-6.0	-6.0	+0.0	+0.5, -0.5		12.59	-4.2	-4.3	-0.1	+0.5, -0.5
1.59	-4.6	-4.7	-0.1	+0.5, -0.5	- 1	15.85	-6.3	-6.2	+0.1	+0.5, -0.5
2.00	-3.4	-3.5	-0.1	+0.5, -0.5	- 1	19.95	-8.2	-8.2	+0.0	+0.5, -0.5
2.51	-2.2	-2.2	+0.0	+0.5, -0.5	- 1	25.12	-10.1	-10.2	-0.1	+0.5, -0.5
3.16	-0.9	-1.0	-0.1	+0.5, -0.5	- 1	31.62	-12.1	-12.2	-0.1	+0.5, -0.5
3.98	+0.0	+0.0	+0.0	+0.5, -0.5	- 1	39.81	-14.2	-14.3	-0.1	+0.5, -0.5
5.01	+0.4	+0.4	+0.0	+0.5, -0.5	- 1	50.12	-16.3	-16.4	-0.1	+0.5, -0.5
6.31	+0.1	+0.1	+0.0	+0.5, -0.5	- 1	63.10	-18.7	-18.8	-0.1	+0.5, -0.5
7.94	-1.0	-1.0	+0.0	+0.5, -0.5	- 1	79.43	-21.6	-21.6	+0.0	+0.5, -0.5

This instrument is in compliance with BS 6841:1987 for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Wj Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s^2 (dB reference = $1e-6 \text{ m/s}^2$) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wj weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-30.2	-30.4	-0.2	+1.0, -998.0	7.94	+0.1	+0.1	+0.0	+0.0, +0.0
0.13	-26.2	-27.5	-1.3	+1.0, -998.0	10.00	+0.3	+0.2	+0.0	+0.5, -0.5
0.16	-22.3	-23.1	-0.8	+1.0, -998.0	12.59	+0.2	+0.2	+0.0	+0.5, -0.5
0.20	-18.4	-18.9	-0.5	+1.0, -998.0	15.85	+0.2	+0.1	+0.0	+0.5, -0.5
0.25	-14.8	-15.2	-0.4	+1.0, -1.0	19.95	+0.1	+0.1	+0.0	+0.5, -0.5
0.32	-11.6	-11.8	-0.2	+1.0, -1.0	25.12	+0.1	+0.0	+0.0	+0.5, -0.5
0.40	-9.1	-9.3	-0.2	+0.5, -0.5	31.62	+0.0	+0.0	+0.0	+0.5, -0.5
0.50	-7.6	-7.7	-0.1	+0.5, -0.5	39.81	-0.1	-0.1	+0.0	+0.5, -0.5
0.63	-6.8	-6.9	-0.1	+0.5, -0.5	50.12	-0.3	-0.3	+0.0	+0.5, -0.5
0.79	-6.4	-6.5	+0.0	+0.5, -0.5	63.10	-0.6	-0.7	+0.0	+0.5, -0.5
1.00	-6.3	-6.4	-0.1	+0.5, -0.5	79.43	-1.5	-1.5	+0.0	+0.5, -0.5
1.26	-6.3	-6.3	+0.0	+0.5, -0.5	100.00	-3.0	-3.0	+0.1	+0.5, -0.5
1.59	-6.3	-6.4	+0.0	+0.5, -0.5	125.90	-5.4	-5.4	+0.1	+1.0, -1.0
2.00	-6.3	-6.4	+0.0	+0.5, -0.5	158.50	-8.6	-8.5	+0.2	+1.0, -1.0
2.51	-6.2	-6.2	+0.1	+0.5, -0.5	199.50	-12.3	-12.1	+0.2	+1.0, -998
3.16	-5.6	-5.7	-0.1	+0.5, -0.5	251.20	-16.1	-15.9	+0.3	+1.0, -998
3.98	-4.1	-4.1	+0.0	+0.5, -0.5	316.20	-20.0	-19.8	+0.3	+1.0, -998
5.01	-2.0	-2.0	+0.0	+0.5, -0.5	398.10	-24.0	-23.8	+0.3	+1.0, -998
6.31	-0.5	-0.5	+0.0	+0.5, -0.5					,

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Wk Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s^2 (dB reference = $1e-6 \text{ m/s}^2$) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Wk weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).




Frequency (Hz)

Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
0.10	-30.1	-30.7	-0.6	+1.0, -998.0	7.94	+0.3	+0.3	+0.0	+0.0, +0.0
0.13	-26.1	-27.5	-1.3	+1.0, -998.0	10.00	-0.1	-0.1	+0.0	+0.5, -0.5
0.16	-22.2	-23.2	-1.0	+1.0, -998.0	12.59	-0.9	-0.9	+0.0	+0.5, -0.5
0.20	-18.4	-19.0	-0.7	+1.0, -998.0	15.85	-2.2	-2.2	+0.0	+0.5, -0.5
0.25	-14.7	-15.2	-0.5	+1.0, -1.0	19.95	-3.9	-3.9	+0.0	+0.5, -0.5
0.32	-11.6	-11.8	-0.3	+1.0, -1.0	25.12	-5.8	-5.9	+0.0	+0.5, -0.5
0.40	-9.1	-9.3	-0.2	+0.50.5	31.62	-7.9	-7.9	+0.0	+0.5, -0.5
0.50	-7.6	-7.7	-0.1	+0.50.5	39.81	-10.0	-10.0	+0.0	+0.5, -0.5
0.63	-6.8	-6.9	-0.1	+0.50.5	50.12	-12.2	-12.3	-0.1	+0.5, -0.5
0.79	-6.4	-6.5	-0.1	+0.50.5	63.10	-14.6	-14.7	-0.1	+0.5, -0.5
1.00	-6.3	-6.4	-0.1	+0.5, -0.5	79.43	-17.5	-17.5	+0.0	+0.5, -0.5
1.26	-6.3	-6.3	+0.0	+0.50.5	100.00	-21.0	-21.0	+0.1	+0.5, -0.5
1.59	-6.1	-6.2	+0.0	+0.50.5	125.90	-25.5	-25.4	+0.1	+1.0, -1.0
2.00	-5.5	-5.6	-0.1	+0.50.5	158.50	-30.7	-30.5	+0.2	+1.0, -1.0
2.51	-4.0	-4.0	+0.0	+0.50.5	199.50	-36.3	-36.1	+0.2	+1.0, -998
3.16	-1.9	-1.9	+0.0	+0.50.5	251.20	-42.2	-41.9	+0.3	+1.0, -998
3.98	-0.3	-0.4	-0.1	+0.5, -0.5	316.20	-48.1	-47.9	+0.2	+1.0, -998
5.01	+0.3	+0.3	+0.0	+0.5, -0.5	398.10	-54.1	-53.9	+0.2	+1.0, -998
6.31	+0.5	+0.4	+0.0	+0.50.5	I				

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.

Quest Technologies Model: HAVPro; Serial Number: 03001 Certificate of X Ws Electrical Conformance

This Type 1 Human Vibration Meter was calibrated using a reference 79.6 Hz sine wave at a level of 0.100 Vrms. This calibration level is equivalent to 140.0 dB or 10.00 m/s² (dB reference = 1e-6 m/s²) with an accelerometer sensitivity of 98.1 mV/g. The instrument's frequency response (Ws weighted, 20 dB gain, ICP input) was then electrically tested as specified in ISO 8041:1990(E).



Freq (Hz)	Theor	Measured	Error	Tolerance	Freq (Hz)	Theor	Measured	Error	Tolerance
1 26	-60.0	-59.5	+0.5	+2.0, -998.0	100.00	+0.0	+0.0	+0.0	+0.5, -0.5
	-52.0	-51.9	+0.1	+2.0, -998.0	125.90	+0.0	+0.0	+0.0	+0.5, -0.5
2.00	-44.0	-43.9	+0.1	+2.0, -998.0	158.50	+0.0	+0.0	+0.0	+0.5, -0.5
2.51	-36.0	-35.9	+0.1	+2.0, -2.0	199.50	+0.0	+0.1	+0.0	+0.5, -0.5
	-28.0		+0.1		251.20				
		-27.9		+2.0, -2.0		+0.0	+0.1	+0.1	+0.5, -0.5
3.98	-19.9	-19.8	+0.1	+2.0, -2.0	316.20	+0.0	+0.1	+0.1	+0.5, -0.5
5.01	-12.2	-12.1	+0.1	+2.0, -2.0	398.10	+0.0	+0.2	+0.2	+0.5, -0.5
6.31	-5.3	-5.3	+0.0	+2.0, -2.0	501.20	+0.0	+0.2	+0.2	+0.5, -0.5
7.94	-1.5	-1.4	+0.1	+2.0, -2.0	631.00	+0.0	+0.2	+0.2	+0.5, -1.0
10.00	+0.0	-0.2	-0.2	+0.5, -1.0	794.30	+0.0	+0.0	+0.0	+0.5, -1.0
12.59	+0.0	+0.0	+0.0	+0.5, -1.0	1000.00	+0.0	-0.6	-0.6	+0.5, -1.0
15.85	+0.0	+0.0	+0.0	+0.5, -1.0	1259.00	-1.7	-2.2	-0.5	+2.0, -2.0
19.95	+0.0	+0.0	+0.0	+0.5, -0.5	1585.00	-4.3	-5.3	-0.9	+2.0, -2.0
25.12	+0.0	+0.0	+0.0	+0.5, -0.5	1995.00	-9.8	-10.1	-0.3	+2.0, -2.0
31.62	+0.0	+0.0	+0.0	+0.5, -0.5	2512.00	-16.3	-17.1	-0.8	+2.0, -2.0
39.81	+0.0	+0.0	+0.0	+0.5, -0.5	3162.00	-25.8	-25.7	+0.1	+2.0, -2.0
50.12	+0.0	+0.0	+0.0	+0.5, -0.5	3981.00	-36.0	-35.5	+0.5	+2.0, -2.0
63.10	+0.0	+0.0	+0.0	+0.5, -0.5	5012.00	-44.0	-49.8	-5.8	+2.0, -998.
79.43	+0.0	+0.0	+0.0	+0.0, +0.0	6310.00	-52.0	-71.5	-19.5	+2.0, -998.
					7943.00	-60.0	-71.2	-11.2	+2.0, -998.
					10000 00	-68 0	-69 9	-1 9	+2 0 -998

This instrument is in compliance with ISO 8041:1990(E) for Type 1 human vibration meters when used with a Type 1 accelerometer.



Miscellaneous Information

This appendix contains additional information about the AC and DC outputs and measurement ranges for Hand-arm and Whole Body measurements.

DC Output Calibration

Since the sensitivity will vary a little from unit to unit, the DC output sensitivity should be calibrated, or measured, before it is used. Follow these steps to measure the DC output sensitivity.

Step 1 Calibrate the HAVPro for the accelerometer that will be used.

Step 2 Setup the HAVPro with the following settings:

a. Operating Mode = Vibration

b. Averaging = Slow

c. Auto Store = Off

d. Weighting = Fc (all channels)

e. Integration = None

f. AC/DC Output = DC: rms (all channels)

Step 3 The gain setting depends upon the sensitivity of the accelerometer being used. The table below shows the appropriate gain setting (for all chan-

5/2/03 E-1

nels) based on the sensitivity of the accelerometer. The values in the table assume that a calibrator that vibrates 1g rms and 159.15 Hz, will be used.

Gain setting for various accelerometer sensitivities

	1 mV/g	10 mV/g	100 mV/g
Gain	60 dB	40 dB	20 dB

- **Step 4** Connect a DC rms voltmeter to the DC output.
- **Step 5** Turn on the calibrator and start the HAVPro running. The HAVPro should display an Arms level of 1 g.
- **Step 6** Note the voltage reading on the voltmeter. The voltage corresponds to 1 g rms of acceleration. The voltage will typically be about 600 mV for a 1 g rms input signal.
- Step 7 Stop and Reset the HAVPro. Reduce the calibrator's output level to 0.1 g rms. If this isn't possible, change the HAVPro's weighting to Wh (Hand-Arm mode). The Wh weighting will attenuate the calibrator's signal to 0.1 g rms (an attenuation of 20.0 dB).
- **Step 8** Turn on the calibrator and start the HAVPro running. The HAVPro should display an Arms level of 0.1 g.
- **Step 9** Note the voltage reading on the voltmeter. The voltage corresponds to 0.1 g rms of acceleration. The voltage will typically be about 500 mV for a 0.1 g rms input signal.
- **Step 10** The DC output uses a logarithmic scale. The formula for the sensitivity is:

DC output sensitivity =
$$\frac{\text{(voltage at 1g) - (voltage at 0.1g)}}{20 \text{ dB}}$$

NOTE: Using the typical values of 600 mV (1g) and 500 mV (0.1g), the calculated sensitivity would be 5 mV/dB. Note that the sensitivity is the same regardless of the DC output setting (i.e. rms, sum, min, max, peak).

Step 11 To convert a DC output voltage to units of g, use the following formula:

 $DC\ output\ (g) = 10^{[(present\ voltage)\ -\ (voltage\ @\ 1g)]\ /\ (DC\ output\ sensitivity)\ x\ 20}$

NOTE: The formula is the same regardless of whether the DC output is being used to measure rms, min, max, or peak acceleration. The only difference is the reference voltage (i.e. the voltage @ 1g). If the DC output is set for rms, min, or max, the reference voltage is the voltage @ 1g rms. If the DC output is set to peak, the reference voltage is the voltage @ 1g peak.

AC/DC Outputs

DC Output

For all of the Analog AC and Analog DC outputs, the output impedance of the HAVPro is 475 ohms. For minimal error, connect to instruments with an input impedance of greater than 100,000 ohms when making AC or DC output measurements.

DC output sensitivity = 5 mV/dB (typical). The level varies between 0 Vdc to 1.0 Vdc.

Since the sensitivity is fixed at approximately 5 mV/dB, the DC output signal is not affected by the user's selection for "display units" or the user's selection of the dB reference value (i.e. 10⁻⁶ m/s² or 10⁻⁵ m/s²).

5/2/03 E -3

The DC output is tied directly to the rms, min, max, and peak values measured by the HAVPro; therefore, the DC output signal is not available if the instrument has been RESET. If the instrument is in a RESET condition, the DC output level will be at approximately -300 mV.

The DC output range covers the entire measurement range of the HAVPro. In other words, the DC output signal level is not affected by the gain settings.

AC Output

The maximum signal produced by the AC output is approximately 0.5 Vrms. However, the maximum input level measurable by the HAVPro is approximately 5.0 Vrms (a difference of 20 dB). Therefore, in order for the HAVPro's AC output to function properly with each range (i.e. gain settings of 0, 20, 40, and 60 dB), the HAVPro's gain settings also affect the AC output signals. For example, with a gain setting of 0 dB, the HAVPro can measure input signals as large as 5.0 Vrms. Since these signals exceed the AC output range, they are attenuated to 0.5 Vrms (a gain of -20 dB) so that they can be reproduced by the AC output. The table below shows the correlation between input signal level and AC output signal level.

AC Output Gain

RANGE (Gain Setting)	INPUT Maximum Signal Level (Vrms)	AC OUTPUT Gain	AC OUTPUT Maximum Signal Level (Vrms)
0 dB	5.0	-20 dB	0.5 Vrms
20 dB	0.5	0 dB	0.5 Vrms
40 dB	0.05	+20 dB	0.5 Vrms
60 dB	0.005	+40 dB	0.5 Vrms

Typical Measurement Ranges for Hand-Arm and Whole Body Measurements

ICP Accelerometers

Hand-Arm (Wh) and Whole Body (WB, Wc, Wd, We, Wb, Wf, Wk)

	1 mV/g		10 n	nV/g	100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g	
0 dB	5-5000	90-7000	0.5-500	9-700	0.05-50	0.9-70	
20 dB	0.5-500	9-700	0.05-50	0.9-70	0.005-5	0.09-7	
40 dB	0.0'5-50	0.9-70	0.005-5	0.09-7	0.0005-0.5	0.009-0.7	

Hand-Arm (Wh)

	1 mV/g		10 n	ıV/g	100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g	
60 dB	0.01-5	0.2-7	0.001-0.5	0.02-0.7	0.0001-0.05	0.002-0.07	

Whole-Body (WB, Wg)

1 mV/g		$10~\mathrm{mV/g}$		100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
60 dB	0.02-5	0.3-7	0.002-0.5	0.03-0.7	0.0002-0.05	0.003-0.07

5/2/03 E -5

Whole-Body (Wc, Wd, We)

1 mV/g		$10~\mathrm{mV/g}$		100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
60 dB	0.05-5	0.8-7	0.005-0.5	0.08-0.7	0.0005-0.05	0.008-0.07

Whole-Body (Wb, Wf, Wk)

1 mV/g		10 mV/g		100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
60 dB	0.03-5	0.5-7	0.003-0.5	0.05-0.7	0.0003-0.05	0.005-0.07

Notes

- 1. The data in the above tables was calculated using the dBuV range data in the HAVPro User Manual.
- 2. The data in the above table was obtained by electrically testing the HAVPro.
- 3. The data is based on ideal accelerometers (the noise floor and upper limit of the accelerometer were not considered).

Typical Measurement Ranges for General Purpose Vibration Measurements

ICP Accelerometers

Fa, Fb, Fc, Ws Weighting

1 mV/g			10 mV/g		100 mV/g	
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
0 dB	5-5000	90-7000	0.5-500	9-700	0.05-50	0.9-70
20 dB	0.5-500	9-700	0.05-50	0.9-70	0.005-5	0.09-7

Fa Weighting

1 mV/g		10 mV/g		100 mV/g		
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
40 dB	0.06-50	1.1-70	0.006-5	0.11-7	0.0006-0.5	0.011-0.7
60 dB	0.04-5	0.8-7	0.004-0.5	0.08-0.7	0.0004-0.05	0.008-0.07

Fb, Fc, Ws Weighting

1 mV/g			10 mV/g		100 mV/g	
Gain	RMS Range g	Peak Range g	RMS Range g	Peak Range g	RMS Range g	Peak Range g
40 dB	0.1-50	1.8-70	0.01-5	0.18-7	0.001-0.5	0.018-0.7
60 dB	0.04-5	0.8-7	0.004-0.5	0.08-0.7	0.0004-0.05	0.008-0.07

5/2/03 E -7

Notes

- 1. The data in the above tables was calculated using the dBuV range data in the HAVPro User Manual.
- 2. The data in the above table was obtained by electrically testing the HAVPro.
- 3. The data is based on ideal accelerometers (the noise floor and upper limit of the accelerometer were not considered).



Service/Warranty Policy

Quest Service Policy

Congratulations! You have purchased one of the finest instruments available, manufactured by one of the most respected names in safety & industrial hygiene instrumentation. Your instrument is backed by a limited warranty that seeks complete customer satisfaction. Should your instrument require service for any reason, you can expect prompt and courteous attention.

You must obtain a return authorization <u>prior to shipment</u>. We reserve the right to refuse any shipments forwarded without prior authorization.

The following information will expedite the service process and is required when obtaining return authorization:

- 1.Model and serial number of each instrument.
- 2.Description of work required and symptoms of any failures for each instrument.
- 3.VISA, MasterCard or American Express credit card -- or -- company purchase order number (non-warranty service only).
- 4.Billing and/or return shipping addresses.

Use one of the methods below to obtain return authorization, service pricing and shipping instructions.

International Customers

Contact your local, factory-authorized distributor from whom the product was purchased. To obtain the name of the local factory-authorized distributor, contact us via email at service@quest-technologies.com, via telephone at +(1)-262-567-9157 or via fax at +(1) 262-567-4047.

5/2/03 F-1

U.S.A Customers Only

- ·Go to the service section of our web site at www.quest-technologies.com.
- ·Contact us via email at service@quest-technologies.com
- ·Contact us at (800) 245-0779. Office hours are 8:00 AM to 5:00 PM U.S. Central Time.

Quest Warranty Policy

Quest Technologies warrants our instruments to be free from defects in materials and workmanship for one year under normal conditions of use and service. For U.S.A. customers, we will replace or repair (our option) defective instruments at no charge, excluding batteries, abuse, misuse, alterations, physical damage, or instruments previously repaired by other than Quest Technologies. Microphones, sensors, printers, and chart recorders may have shorter or longer warranty periods. This warranty states our total obligation in place of any other warranties expressed or implied. Our warranty does not include any liability or obligation directly resulting from any defective instrument or product or any associated damages, injuries, or property loss, including loss of use or measurement data.

For warranty outside the U.S.A., a minimum of one year warranty applies subject to the same limitation and exceptions as above with service provided or arranged through the authorized Quest distributor or our Quest European Service Laboratory. Foreign purchasers should contact the local Quest authorized sales agent for details.

Index

A	Connections on the HVM100 9-1
AC Output E-4	D
AC Output Gain E-4	Data Communications A-3
AC/DC Connector Output Connector	Data Key7-7
9-6	Data Storage A-2
AC/DC Output Settings3-7	Date and Time 3-13
AC/DC Outputs E-3	DC Output3-7,
Accelerometer Selection 1-4	E-3
Accelerometer Type3-1	DC Output Calibration E-1
Alpha Numeric Menu function 2-1	Declaration of Conformity A-4
Auto Range4-1	Digital DisplayA-3
В	Dimensions/Weight A-3
Band Limiting Filters1-8	Direct InputA-5
Batteries8-1	Display Units3-2
battery voltage8-1	E
Baud Rate3-8	Effects of Humidity A-2
C	Effects of Magnetic Fields A-2
Cal Level4-3	Effects of Mechanical Vibrations A-2
Calendar A-3	Effects of Temperature A-2,
Calibration 4-3	E-2
Calibration Frequency A-6	Electrical Impedance A-4
Calibration Vibration A-7	Erasing Files3-9
CE Mark A-4	Erasing Setups3-10
CharacteristicsA-1	External Power 8-4
Charge InputA-5	External Power Connection 9-5
Charge mode sensors1-4	Larson Davis adapter9-5
Checking Battery Voltage 8-1	Pinout9-5
Clock A-3	Frequency range1-5
Connections	Frequency weighting1-7
AC/DC Output Connector 9-1	Frequency Weighting Curves . A-7
External Power9-1 Input Connector9-1	Fa (Flat 0.4 Hz to 100 Hz) A-7
Serial Port9-1	Fb (Flat 0.4 Hz to 1260 Hz) A-9

5/2/03 Index

Fc (Flat 6.3 Hz to 1260 Hz), Wh, and Ws	Menu Navigation2-1
A-11 WB (Whole Body)A-15	Modes of Operation1-7
Wc, Wd, We, Wj, and WkA-13	Band Limiting Filters1-8
G	Frequency Weighting1-7
Gain4-2	N
General CharacteristicsA-1	new batteries8-1
Н	0
Hand Arm	OutputsA-4
Wh1-7	Overload Detection7-2
Hand Arm Mode Weighting2-9	P
Handshaking3-8	Power SupplyA-3
Headers3-11	Powering the HVM1008-1
History Key7-3	Print History3-9
HumidityA-2	Printer Cables5-2
Hyperterminal5-2	Printing5-1
I	Printing to a Windows Hypertermina
ICP accelerometers1-4	5-2
ICP InputA-5	R
Indexed Menu Function2-3	Range Key4-1
Installing new batteries8-1	Auto Range4-1
Integration3-3	Cal Level4-3 Calibrate X,Y,Z4-3
K	Gain X,Y,Z4-2
Key Board Functions2-4	Reference Acceleration4-5
L	Sensitivity X,Y,Z4-4
	Range Menu4-1
Language3-13	Real-time Clock/CalendarA-3
Limits of Temperature and Humidity A-2	Recall Key
M	Recalling a File6-10 Recalling a Setup6-7
Magnetic FieldsA-2	Recalling Data6-1
Mechanical VibrationsA-2	Recalling Setups6-1
Menu Function	Reference Acceleration4-5,
Indexed2-3	A-6
Menu function	Reference Calibration Frequency A-
Alpha Numeric2-1	6

Index 5/2/03

Reference Calibration Vibration A-7	Baud Rate3-8
remaining battery voltage 8-1	Handshaking3-8
Run/Stop Key7-1	Date and Time3-13
Run-time ClockA-3	Display Units
	Erase All Files
S	Header 1,2,3 3-10
Screen Symbols7-1	Integration3-3
Second History7-6	Language3-13
Selecting a Transducer1-4	Print History Selection3-9
Sensitivity4-4	Sum Factor X,Y, Z3-4
Serial Interface Port9-2	Tools Menu3-1
Cables used9-3	transducer1-4
Pinout9-2	Transducer Connection 9-4
Serial Port5-1	Pinout9-4
Setup Key2-5	Transducers Electrical Impedance
2-5 2nd History2-5	A-4
Auto Store2-5	Transverse sensitivity1-5
Averaging Time2-5	Type PrecisionA-1,
Time History Settings2-5	F-1
Mode Selection2-5	Typical Measurement Ranges for
Store Time2-5	• • • • • • • • • • • • • • • • • • • •
Stabilization TimeA-2	General Purpose Vibration Measure-
Stop Key7-1	ments E-7
Store Key	Typical Measurement Ranges for
Storing a File6-4	Hand-Arm and Whole Body Mea-
Storing a Setup6-1	surements E-5
Storing Data6-1	Typical Measurements Ranges A-19
Storing Setups6-1	Hand Arm - Wh A-21
Sum Factor	Vibration - Fa
T	Whole Body - WB
•	Whole Body - Wc
Taking Measurements7-1	Whole Body - Wd, We A-24
TemperatureA-2	Whole Body - Wg A-25
Time History Settings2-6	Whole Body - Wj, Wk
Tools Key3-1	U
AC/DC Output 3-4	Under-Range indicator7-3
AC/DC Output Settings3-7	Units 3-2
Accelerometer Type3-1	Using External Power8-4

5/2/03 Index

٧

Vibration	
Fa (0.4 Hz to 100 Hz)1	-7
Fb (0.4 Hz to 1250 Hz)1	
Ws (Severity)1	-7
Vibration Mode Weighting2	-9
VibrationFc (6.3 Hz to 1250 Hz)	1-7
Viewing Data7	-1
Viewing Time History7	-6
W	
Weight	\ -3
Whole Body	
WB Wc Wd We Wg Wj Wk1	-7
Whole Body Weighting Mode 2	-10

Index 5/2/03